



# MULTICAM

## RELEASE NOTE **VERSION 11.02.87**

Date: June 2015

WARNINGS .....	2
NEW FEATURES .....	2
BUG FIXES.....	6
KNOWN ISSUES & LIMITATIONS .....	11
ISSUES .....	11
LIMITATIONS.....	12
COMPATIBILITY.....	15
HARDWARE .....	15
XNET.....	15
CLIPS.....	16
HYPERMOTION VISION RESEARCH CAMERA .....	16

### Corporate

Headquarters  
+32 4 361 7000

### North & Latin America

Headquarters  
+1 947 575 7811

### Asia & Pacific

Headquarters  
+852 2914 2501

### Other regional offices

Available at  
[www.evs.com/contact](http://www.evs.com/contact)

## WARNINGS

- > **Setup parameters (Shift-F2 and remote setup) may be reset after the upgrade from Multicam 10.0x. Please check all your parameters after the upgrade**
- > **V3X modules with SN between 98 and 259 do not allow to output in 3G-SDI on J2 connector, which is mandatory to use the 8-channel layout of the Quad-MTPC**
- > Multicam 11.02 must be used with version 3.03 and above of the XHub
- > The maximum number of pre-installed Multicam versions allowed on a server is 5
- > Default XFile parameter is reset after upgrade from Multicam 11.00 to 11.02

## NEW FEATURES

### IN 11.02.87

- > No new features, bug fixing only

### IN 11.02.85

- > No new features, bug fixing only

### IN 11.02.83

- > No new features, bug fixing only

### IN 11.02.81

- > No new features, bug fixing only

### IN 11.02.80

- > Support of XS 4RU

### IN 11.02.76

- > LSM Connect 2.0 with support for Epsio.FX

### IN 11.02.75

- > No new features, bug fixing only

### IN 11.02.72

- > No new features, bug fixing only

### IN 11.02.68

- > Compatibility with LSM.Connect
- > LSM advanced TimeLine editing
  - Replay speed
  - 4-point edit
  - Split element
  - Insert / overwrite element

### IN 11.01.79

- > No new features, bug fixing only

### IN 11.01.77

- > No new features, bug fixing only

### IN 11.01.76

- > No new features, bug fixing only

**IN 11.01.74**

- > Compatibility with IPDirector 6.0

**IN 11.01.50**

- > No new features, bug fixing only

**IN 11.01.47**

- > Support of hypermotion cameras: NAC Hi-Motion II

**IN 11.01.25**

- > XT3 Ultra-Motion mode for I-MOVIX 6/10x camera
- > Support of Sony HDC-2500 camera for Supermotion 2x on 3G-SDI on XT2+ with V3X and XT3. Examples of configurations:
  - 1 SLSM 2x 3G + 3 REC HD + 2 PLAY HD
  - 2 SLSM 2x 3G + 2 REC HD + 2 PLAY HD
  - 3 SLSM 2x 3G + 2 PLAY HD
- > Support of new hypermotion cameras:
  - Sony integration of Vision Research camera
  - FOR-A VFC-7000
- > Support of HCTX Gigabit module rev. A7
- > Remote lock function by pressing CLEAR+MENU
- > On the VGA clip screen, display of a growing clip will alternate between clip name and "creating xx%"

**IN 11.00.71**

- > Support of Xscreen
  - Simple media management tool working in combination with XTnano or XSense remote
- > Support of LinX v2
  - Support of LSM playlists
  - XNet management (visibility of servers connected to SDTI, ability to load a network clip, ...)

**IN 11.00.62**

- > No new features, bug fixing only.

**IN 11.00.58**

- > More recording channels available on XT3 6RU, XT3 4RU and XTnano with V3X boards. These are available in specific in/out configurations, including:
  - XT3 6RU 8 channels (SD and HD)
    - 1 SLSM 3x + 4 REC + 1 PLAY
    - 6 REC + 2 PLAY
    - 1 SLSM 3x + 3 REC + 2 PLAY
    - 2 SLSM 3x + 2 PLAY
    - 1 SLSM 2x + 4 REC + 2 PLAY
    - 2 SLSM 2x + 2 REC + 2 PLAY
    - 3 SLSM 2x + 2 PLAY
    - 5 REC + 3 PLAY
    - 4 REC + 4 PLAY
    - 1 SLSM 3x + 1 REC + 4 PLAY
    - 1 SLSM 2x + 2 REC + 4 PLAY
    - 2 SLSM 2x + 4 PLAY

- Limitations: the Dual Channel mode allows the use 1 codec module to record 2 channels ; it does not allow to use 1 codec module to create 2 independent playback channels. It means that all 8-ch configurations are not possible. For example, 2 REC + 6 PLAY, or 8 PLAY is not allowed.
- 3D 6-ch and 1080p 6-ch (dual and single link) also supported
- New multiviewer configuration for 6 cameras + 2 PGM
- XT3 4RU 7 channels (SD and HD)
  - 6 REC + 1 PLAY
  - 1 SLSM 3x + 3 REC + 1 PLAY
  - 2 SLSM 3x + 1 PLAY
  - 3 SLSM 2x + 1 PLAY
  - 4 REC + 2 PLAY
  - 1 SLSM 3x + 1 REC + 2 PLAY
  - 1 SLSM 2x + 2 REC + 2 PLAY
  - 2 SLSM 2x + 2 PLAY
- Limitations: the Dual Channel mode allows the use 1 codec module to record 2 channels; it does not allow to use 1 codec module to create 2 independent playback channels. It means that all 6-ch configurations are not possible. For example, 2 REC + 4 PLAY, or 6 PLAY is not allowed.
- 3D 4-ch and 1080p 4-ch (dual and single link) also supported
- XTnano 6 channels
  - 4 REC + 2 PLAY
  - 1 SLSM 3x + 1 REC + 2 PLAY
  - 1 SLSM 2x + 2 REC + 2 PLAY
  - 2 SLSM 2x + 2 PLAY
- Limitation: only the above 6-channel configurations are available on XTnano
- > New XSnano in 4RU chassis: 4-channel server controlled by protocols (VDCP, Sony, Odetics, XtenDD35)
- > New server configuration on XTnano allowing exclusive control by protocols (VDCP, Sony, Odetics, XtenDD35)
- > Mix on 1 channel available on XT3, XS and XT[2]+
  - Users in Spotbox configurations usually need to control two channels in PGM/PRV to play back a playlist with effects. With the mix on one channel activated, they can play back a playlist with effects on PGM1 while using PGM2 to play back something else.
  - Multicam LSM users in 2 PGM mode can use the load playlist parameter to decide if they want to use the second PGM2 to play effects or be in "conditional" mode and play back in cut on one channel. With the mix on one channel option, users can play back a playlist with effects using only one PGM output instead of two.

- > New configuration tools:
  - On the VGA, EVS and AVCFG are merged into MulSetup application which also covers the SHIFT+F2 configuration screens that have been completely reorganized
  - Configuration organized in categories, technical vs operational
  - Easier audio configuration
  - On the remote, parameters have been reorganized as well to reflect VGA categorization
  - New configuration interface accessible via a web browser connecting to the PC-LAN IP address.
- Parameters that can be changed without rebooting Multicam
  - Audio configuration
  - Protocols assignment
  - Monitoring configuration
  - All 'operational' parameters
- Parameters still requiring Multicam to reboot
  - Number of record/playback channels
  - Video codec
  - Video standard.
  - Network IP addresses
- > In playlist mode, be able to add cut point and split one clip in two or any parts for easier edition.
- > EditRec improvements
  - Redo function via EVS VGA menu which allows Undo function cancelling.
  - Add 1080p50/1080p60 compatibility
  - Add 3D compatibility
  - Add AVC Intra compatibility
  - Final Cut Pro auto edit compatible
- > Supermotion improvement in 1080i DVCPro and AVC-Intra video available on XT3 allowing smooth replay above 33% or 50% speed

## BUG FIXES

### IN 11.02.87

- > When *Call Channel* is set to no, F3 would load clips on an uncontrolled PGM (MUL-463)
- > When in a playlist, calling a clip from the VGA in CLIP mode would unload the playlist (Bug ID 91421)

### IN 11.02.85

- > Archive flag of new clips created from a copy of another clip would not be reset (Bug ID 92078)
- > Network problems on PC-LAN would occur after downgrading from a Multicam version that supports the Truck Manager (Bug ID 92011)

### IN 11.02.83

- > Unicode was not supported for playlist name (Bug ID 91527)
- > PS/2 keyboard lock when pressing Caps Lock and other keys very quickly (Bug ID 85668)

### IN 11.02.81

- > *Call Channel* in the playlist screen sometimes load clips with camera ID (e.g. 111A) on the wrong player (Bug ID 90999)
- > When a GPI controls a PGM for PLAY, supermotion clips in playlist are not started with the standard replay speed (Bug ID 90983)

### IN 11.02.80

- > Playlists created with IPDirector and played using a GPI trigger start with 117% speed (Bug ID 89704)
- > *Call Channel* loads the clip on the PGM controlled by the LSM Remote rather than on the configured PGM (Bug ID 88751)
- > With Odetics, a request to go to a timecode which does not exist causes the channel to go idle rather than being ignored (Bug ID 88656)
- > AVSP OSD audio meters are not displayed on the recorder channels (Bug ID 78498)

### IN 11.02.75

- > Redundant IPDP links on RS422 do not failover with full control from IPDirector (Bug ID 88770)
- > With HS-870 MTPC, LinX port is not initialized properly if the PC-LAN cable is not connected before starting Multicam (Bug ID 85877)

### IN 11.02.72

- > Postroll OSD in playlist mode not consistent with parallel IPDP control (Bug ID 87003)
- > Only 1 XSense Remote can be used on XSnano (Bug ID 86080)
- > AVSP command *ChangeTimeCodeIn* modifies both LTC and UserTC instead of only the selected target TC (Bug ID 85863)
- > In EditRec mode, the command "Insert With Ripple" fails with duration longer than 40min (Bug ID 84408)

### IN 11.02.68

- > With XRec configuration in HD, down-converted output (J3) of PLAY codec cannot be set to SD (Bug ID 82929)
- > Restart of Multicam is required to apply IPDP main control configuration (Bug ID 82529)
- > GBE discovers mixed IP addresses when cross-connecting GBE1 and GBE2 (Bug ID 82041)
- > Hypermotion camera could not reconnect after losing PC LAN (Bug ID 80764)
- > AVSP OSD audio meters are not displayed on the recorder channels (Bug ID 78499)
- > 'GoTo TC' on Lance controller (SET CUE) ejects clip from player (Bug ID 75905)
- > IPDP port is opened even if no PGM or REC is assigned for IPDP, either main or secondary (Bug ID 39470)
- > PGM1 jumps to E/E when deleting all the clips one by one of a playlist loaded on PGM2 (Bug ID 39435)
- > Pressing space bar will not work when SHIFT is pressed at the same time (Bug ID 39412)

- > 'Sync to' command affects PGM channels that are not controlled (Bug ID 38921)
- > Audio monitoring not displayed correctly in 3 REC + 3 PLAY configuration when activated from the LSM remote (Bug ID 38119)
- > Effect duration is not taken into account on the OSD when editing a playlist to do a replace when Mix on one channel is enabled (Bug ID 35779)

### IN 11.01.79

- > RSAS board not detected properly with HS-873 (Bug ID 39967)
- > Missing ID after add/delete of clips over VDCP (Bug ID 76229)
- > No embedded audio on PGM2 of XTnano/XSnano with CODA65+HCTX (Bug ID 78317)
- > With 3 Remotes, Post-Roll of PGM1 and PGM2 is controlled by PGM3 (Bug ID 79443)
- > Fast-Forward in playlist return to 100% speed at the end of a clip (Bug ID 79498)
- > 2<sup>nd</sup> control of only 1 PGM outputs black (Bug ID 79762)
- > Audio effects cannot be edited on a playlist that was copied over SDTI (Bug ID 79883)

### IN 11.01.77

- > The channel status are wrong after a LinX restart (Bug ID 76891)
- > In EditRec mode, video duration cannot be less than 17 frames. No video on the EditRec OUT channel (Bug ID 77736)
- > In EditRec mode, frame is not recorded when video duration is 1 frame and audio delay is applied (Bug ID 77740)
- > AVSP timeline loses the audio video sync when using the step command inside a transition between two clips (Bug ID 76057)

### IN 11.01.76

- > Tablet is not working with HS870 and Multicam 11.01.74 (Bug ID 77353)
- > Glitches on HD multiviewer output (Bug ID 77110)
- > Dolby E configuration not taken into account when mixing PCM and Dolby E assignments on playout channels (Bug ID 76669, 77773)

### IN 11.01.74

- > With AVSP protocol, OSD is flashing at each transport command (Bug ID 34386)
- > Speed of playback is not displayed on the IPD OSD when in playlist element mode (Bug ID 36562)
- > In 2 PGM mode controlled by IPDdirector, last line of OSD is not masked out on PGM2 when "Display Playlist elements" setting is used (Bug ID 36655)
- > When modifying the TC In of an element in playlist with Mix on one channel enabled, in Edit mode the PRV channel shows the original instead of the modified TC In (Bug ID 37610)
- > Impossible to do Sort TC on PGM3 in cam mode (Bug ID 37673)
- > Wrong OSD on other PGM channels when loading a playlist on PGM1 with Mix on one channel and Load Playlist Conditional enabled (Bug ID 37711)
- > VDCP controller can't get the list of clips when one varID is empty (Bug ID 37955)
- > Creating a sub clip with new mark in mark out does not retain new VarID (Bug ID 37989)
- > Audio in a playlist that is being scrubbed has glitches (Bug ID 38325)
- > When importing a config line from an XT3 onto an XT2+, the Mix on 1 channel parameter gives issues (Bug ID 38536)
- > VDCP Play failed/timeout when restore of the Clip is ongoing (Bug ID 38590)
- > Incrust End Of playlist appears over the video in Playlist edition mode (Bug ID 38826, 38872)
- > Cam Pref not loaded on PRV channel when PRV Ctrl is activated (Bug ID 39056)
- > AVSP OSD tags not working correctly (Bug ID 39157)
- > Server plays at wrong speed 117% when GPI is used to trigger the playout (Bug ID 39196)

- > Issues with split audio editing in 2 PGM mode with 2 remotes, and Mix on one channel enabled (Bug ID 39286)
- > AVSP copy clip: varID truncated to 8 bytes (Bug ID 39320)
- > AB Roll element is skipped when using next (Bug ID 39505)
- > EditRec command "delete content with ripple" does not take into account the duration (Bug ID 39616)
- > Remote is desynchronized while changing Channel/Device on VGA (Bug ID 39686)
- > VDCP : Remaining time isn't correct when a portion of train is loaded (Bug ID 39748)
- > Idle Channel or Source Disconnected when deleting a playlist element in exclusive mode with IPDP secondary control (Bug ID 39763)
- > Insufficient A/V material when making IPEdit with growing clip (Bug ID 39907)
- > When using 2 remotes, editing a playlist and deleting elements on remote 1 blocks remote 2 (Bug ID 39994)

### IN 11.01.50

- > Impossible to edit more than one DELAY/LIVE in an IPD playlist (Bug ID 34764)
- > SDTI network sometimes does not rebuild when there is a mix of XT2 and XT3 servers (Bug ID 39039)
- > Playlist element forever marked ToBeSkip if a restore/copy/transfer of the corresponding clip fails or is aborted (Bug ID 39386)
- > Issue with HCTX board not joining the SDTI network at start-up (Bug ID 39443)

### IN 11.01.47

- > Converting PL with audio split to TL creates desynchronization between audio and video (Bug ID 33394)
- > When working in 2 PGM mode, wrong picture is grabbed by EPSIO (Bug ID 37105)
- > Incomplete protocol list in RS-422 ports assignments from the web configuration tool (Bug ID 37312)
- > Hi-Motion1 - Hitting last cue without having marked any cue point cues up the wrong image (Bug ID 37352)
- > Web configuration not updated after modification done on the VGA (Bug ID 37470)
- > In hypermotion mode, the recorder parameter goes back to the default value after a reboot (Bug ID 37469)
- > When Load Playlist Always mode with Preview control enabled, hitting live disables PRV CTL and quits playlist edit mode (Bug ID 37544)
- > When Mix on 1 channel is enabled in PGM+PRV mode, going into playlist edit mode via the jog shows incorrect TC In for the element loaded on the PRV channel (Bug ID 37349)
- > In hypermotion mode, hitting Last cue on a block in play has no effect (Bug ID 37590)
- > The jog-dial lock does not work when using hypermotion mode (Bug ID 37620)
- > EditRec: "Delete content" function on the VGA does not work (Bug ID 37627)
- > Audio configuration modified following automatic update of Playlist receive page parameter (Bug ID 37723)
- > XNet Monitor displays incorrect values for PCLAN network parameters on servers with HS873 (Bug ID 37900)
- > Impossible to get the list of clips in VDCP with some automation systems (Bug ID 37744)
- > PGM2 Audio Plays out on PGM2 & PGM1 after IPEdit is closed (Bug ID 34044)
- > A GPI IN defined in IPDirector does not work in Multicam LSM mode on channels with exclusive IPDP control (Bug ID 34351).

### IN 11.01.25

- > Default XFile resets automatically when another Xfile comes into the SDTI network and has a lower net number (Bug ID 36640)
- > When mixing two supermotion clips in DVCPPro HD, if the effect duration is not a multiple of 3 fields there will be a video freeze of 3 fields during the transition between the two clips (Bug ID 13635)
- > EditRec audio monitoring issue when in EE mode (Bug ID 34615)
- > AVSP controlled channel interferes with LSM channel (Bug ID 35407)
- > Some USB keys are not detected on HS873 board (Bug ID 35546)



- > REC status returned by Sony protocol even if not recording when in parallel control mode (Bug ID 36321)
- > OSD issues when Sony is defined as 2<sup>nd</sup> control (Bug ID 32459)
- > Parallel Configuration with VDCP F&K should not be accepted (Bug ID 32488)
- > OSD disappears temporarily when doing a Timeline Extend (Bug ID 32640)
- > No OSD on recorders when server is configured with only record channels controlled in VDCP (Bug ID 32656)
- > Server might not boot correctly after BIOS upgrade (Bug ID 35725)
- > GOTO IN is not possible on the 2<sup>nd</sup> remote if a timeline is loaded with the 1<sup>st</sup> remote (Bug ID 32921)
- > Char Out J4 in the Monitoring configuration tab changes from HD to SD when format changes from 1080i to 720p (Bug ID 35509)
- > TC of PGM2 follows the TC of PGM1 when a PL is cued on PGM2 and PGM1 and the play command is given (Bug ID 35631)
- > XSense - Postroll doesn't work on playlists (Bug ID 34405)
- > XSense - The Timeline Receive page value isn't taken into account when doing an extend (Bug ID 34514)
- > Enabling hypermotion after resetting to default value in page 7.OPERATION of the configuration menu lead to incorrect error message when trying to change channel IN/OUT configuration (Bug ID 30772)

## IN 11.00.76

- > Impossible to control the server via VDCP if no PGM/RS-422 port association is done (Bug ID 36052)
- > Multicam installation on HS873 MTPC board will not work with some USB devices (Bug ID 35546)
- > Message "Error: Upgrade BIOS needed" after Multicam 11 installation (Bug ID 35725)
- > After format and install, setting PC LAN IP address is not applied on servers with HS873 (Bug ID 32642)
- > Reduced capacity on servers encoding in M-JPEG after upgrade to Multicam 11.00 (Bug ID 37444)

## IN 11.00.71

- > When using AVSP protocol, audio mix effect is not played on first transition of a timeline (Bug ID 34961)
- > When loading a playlist with Mix on one channel enabled, current duration doesn't take into account the effect duration. (Bug ID 33864)
- > Multicam never boots when video configuration is set to 720p with and genlock type is Tri-Level Sync (Bug ID 34375)
- > When using AVSP protocol, a clear video disk command does not completely restart the Multicam software. (Bug ID 34381)
- > 2<sup>nd</sup> control are not always correctly reported by SNMP protocol in XNet Monitor (Bug ID 34704, 34717)
- > When an EditRec Playlist is created in IPDirector and loaded on an EditRec channel, the Start TC is incorrect (Bug ID 14238)
- > Default XFile value is reset after rebooting server (Bug ID 34530)
- > Aux clips stops at end of PL (Bug ID 34743)
- > AutoMake clip can't be disabled on Cam F (Bug ID 34413)
- > EditRec : Full EE ON doesn't work (Bug ID 34329)
- > Latencies when browsing with BePlay remote (Bug ID 35389)

## IN 11.00.62

- > Clips created on XL[2] show 1 frame delay compared to the corresponding clip on the high res server (Bug ID 32819)
- > When working with network playlists, Multicam can sometimes hang while exiting the application, without any damage to the server content (Bug ID 32515)
- > Incorrect default values for Guardband duration, clip duration, clip postroll on an NTSC configuration (Bug ID 32914)
- > When restoring very small clips via gigabit, some clips can remain blocked in "creating" (Bug ID 33729)

**IN 11.00.58**

- > PLST conditional mode sometimes fails in 3PGM mode (Bug ID 11344)
- > In Split audio mode, the limits of a clip are not updated by changing the type of effect from MIX to CUT (Bug ID 11711)
- > Insert clip from a search fails if a keyword file is selected (Bug ID 13688)
- > Playlist loaded on Remote 2 won't apply IPD channel settings in parallel control mode (Bug ID 14620)
- > In 2 REC + 4 PLAY configurations with 2 remotes and IPDP parallel control, playlist loop setting is disabled on second remote (Bug ID 14568)
- > SORT-TC functionality different between M8 and M10 versions (Bug ID 23126)
- > Trouble when transcoding clip with XTAccess into MPEG2 SD 8Mbps (Bug ID 13422)
- > F9 Connect window list cannot be scrolled by keyboard, after use of tablet (Bug ID 23759)
- > In 720p, playlist cannot be converted in Timeline when clip elements have been retrimmed on odd frames (Bug ID 14176)
- > Cannot enter date under goto TC function in XTnano (Bug ID 14190)
- > GPI 'Previous' is not working in IPD Playlist panel (Bug ID 14236)
- > The image is not centered when enabling the Horizontal Split (Bug ID 14779)

## KNOWN ISSUES & LIMITATIONS

### ISSUES

#### **SINCE 11.02.85**

- > Control of hypermotion camera over RS422 with ASCII protocol does not connect; Control via PC LAN works fine as a workaround (Bug ID 91812)

#### **SINCE 11.02.80**

- > With Odetics in parallel control to an LSM Remote, deleting a clip from a playlist causes the LSM Remote to freeze; pressing [RECORD] unlocks the remote (Bug ID 89292)

#### **SINCE 11.02.68**

- > Cross-fade is not applied when swapping audio tracks on the Short IN of a clip in a playlist (Bug ID 83621)
- > When default copy/move is set to GBE, CAM pref information may get lost (Bug ID 83362)
- > With hypermotion cameras, cue points are not recalled properly when the block is not full (Bug ID 83078)
- > When loading a playlist on a single channel (with Load Playlist set to Conditional), some operation require to press twice on Undo to actually undo the operation (Bug ID 80756)
- > In SD, remote CAM mapped as local CAM may not be synchronized with the local CAM (Bug ID 78920)

#### **SINCE 11.01.77**

- > AVSP does not correctly regenerate TC when clip is added in a timeline (Bug ID 78493)

#### **SINCE 11.01.74**

- > Default Gigabit copy/move takes a few seconds to start (Bug ID 75771)

#### **SINCE 11.01.47**

- > VDCP controller can't get the list of clips when one varID on the server is empty (Bug ID 37955)
- > Issue with Mix on 1 channel configuration when important a config line from XT3 to XT2+ (Bug ID 38536)
- > AVSP OSD tags not working correctly (Bug ID 39157)
- > In AVSP, the remaining time displayed on the OSD uses the Protect OUT of a clip instead of the Short OUT (Bug ID 39129)
- > PGM1 jumps in E/E when deleting all the clips one by one of a playlist loaded on PGM2 (Bug ID 39434)

#### **SINCE 11.01.25**

- > Modifying hypermotion configuration in SHIFT+F2 OPERATION screen can lead to conflicts when LSM remote is in hypermotion mode (Bug ID 35644)
- > OSD Remaining time continues to run when playing out a clip which has reached the end of the guardband (Bug ID 36097)
- > In 2 PGM mode controlled by IPDirector, last line of OSD is not masked out on PGM2 when "Display Playlist elements" setting is used.
- > Speed of playback is not displayed on the OSD when Multicam OSD is enabled on a PGM channel controlled by IPDirector. (Bug ID 36562)

#### **SINCE 11.00.58**

- > PRV channel does not automatically go back to Live when a Timeline loaded for playout is switched to edit mode (Bug ID 23077)
- > In SpotBox mode, wrong colors on audio meters for 3D configurations (Bug ID 36259)

#### **SINCE 10.03.39**

- > When doing massive transfers through one of the the HCTX gigabit ports, the connection can be lost. A warning message will pop up on the VGA, the remote and the monitoring output when the HCTX gigabit module is no longer alive (Bug ID 12910).

## SINCE 09.00.74

- > Using the VDR panel while in Timeline edit mode may result in loss of audio on the PGM (Bug ID 7759, 7690, 7943)
- > Odetics protocol in secondary control : audio slow motion parameter not taken into account (Bug ID 7693, 8710)

## SINCE 08.04

- > In paint/Target mode, load a clip from the remote. Pressing play from the tablet, the clip is played at 100% speed (Bug ID 6616)
- > When the stylus is on the tablet, on the F9 window displaying the remote servers, sometimes it is not possible to use the arrows to navigate through the list (Bug ID 4958)
- > From machine A, play a clip of machine B. It is possible to delete the clip from B although the clip is on air (Bug ID 6338)
- > It is impossible to load a timeline in load playlist conditional (Bug ID 5365)
- > The Undo command in playlists does not apply to the "Make Local" command (Bug ID 5515)
- > In split screen mode, audio meters only appear on PGM1, not PGM2 (Bug ID 5056)
- > Do a sort-TC, get the list of results, loading a playlist without first pressing Live. Using the browse button will bring the user back to the browsing in the search result, not in the playlist. (Bug ID 6276)
- > In Loop rec off, when the maximum of the recording capacity has been reached exit the server without creating clips. When restarting the server will reallocate a small amount of the disk capacity to the recorder cache, resulting in losing some recorded images. The workaround is to protect the footage by clipping it before exiting the server. (Bug ID 6798)
- > Go to TC on a User TC in a clip does not always go to the desired TC (Bug ID 6816)

## BEFORE 08.04

- > The default display mode is VGA. When upgrading, the default mode is retained. When pressing ALT-Backspace to toggle between VGA and Video mode inside the Multicam application, this might in some cases causes the system to disconnect from the network. The only solution to reconnect is to exit the application and restart it. This problem does not occur systematically, but avoid using ALT-Backspace inside the Multicam application when possible. Using ALT-Backspace while the Multicam is running can also cause a 00:00:00:00 TC to be marked on the video field recorded at that time.
- > PUSH to a client system: the clip will be copied on the right machine, but in the receive page defined in the setup of the original machine rather than the one defined in the setup of the destination machine.
- > It is not possible for a client to push a clip to another client.
- > On a server XT, create a playlist and load it. If you go back to live and move to another machine the clip that was last loaded on the player, it will be impossible to reload the playlist anymore.
- > Occasionally the clip TC displayed on the remote in timeline mode may not be accurate.
- > Setup Menu, Audio Meters Adjustment : when this parameters is set to 10 or 12dB, the audio meters on the OSD disappear (Bug ID 5639)
- > When loading a clip or playlist after a network train, then marking a cue live, the cue is marked on the local trains, not on the previously loaded network train.
- > Freeze on OUT point in record trains in target tracking doesn't work, in PLAY VAR only. OK in normal play.
- > After having done a search on the remote, the browse function always browses in the results of the clip search, it is not possible to browse in the clips of the remote anymore without pressing "live".

## LIMITATIONS

### SINCE 11.00.71

- > Mix on one channel cannot be used in combination with EPSIO offside line (Bug ID 35001)
- > OSD disappears after deactivation of the IPDP secondary controller while there is a playlist loaded and end of playlist is reached (Bug ID 32516)
- > Some Playlist OSD information can be missing when LSM remote and IPDirector are controlling PGM channels in parallel and OSD is set to a controller different than the one loading the playlist (Bug ID 32533).
- > When in the Multicam Setup page, technical OSD can be corrupted when focus is set to configuration lines for which the video standard does not correspond to the genlock of the server (Bug ID 32791).

### SINCE 10.04.18

- > With Hypermotion cameras, wrong OSD color for 1 or 2 seconds when pressing LastCue button (Bug ID 14021)
- > Clips are not logged in AsRunLog when the playout is interrupted (Bug ID 13241)

- > *Other Angle* function in Playlist edit mode does not work with clips with TC more than 24h behind the head of the record train (Bug ID 13826)
- > With 3 PGM channels, the SDT F9 connect window isn't displayed when there is an IPDP Timeline loaded on PGM1/PGM2 (Bug ID 14074)

## SINCE 10.03.33

- > Push gigabit:
  - Cannot push a SDTI network clip through gigabit to a gigabit only server (Bug ID 12864)
  - When pushing on the fly before saving the clip, changes made on the clip information (name, keywords, rating) are not pushed (Bug ID 12847, 12848)
  - Gigabit push clip ID destinations start from 0 (110, 111, 112,...) while SDTI destination IDs start from 1 (111, 112,...110). (Bug ID 12811)

## SINCE 10.01.57

- > DVCPRO HD 1080i Supermotion is not supported
- > When offside line mode is active or hypermotion mode is active, secondary control is not available on the remote in shift-D.

## SINCE 09.00.47

- > Clip creation from different PGMs controlling distant trains and local trains : mark in/out point successively on the various PGM may reset in/out points (Bug ID 8176)
- > Going into the Remote menu may deactivate a secondary control (Bug ID 8439)
- > Start the server in Spotbox IPDP mode with the "Monitor Out" parameter of the EVS set to "SDI". Until something is loaded on the players (Bug ID 7052)
- > Sony VITC time code is not available in Sony ganged mode, only Sony LTC and Sony Timer mode

## SINCE 08.04

- > Keyword file names must be limited to 8 characters
- > In PGM/PRV mode, playing a network playlist, if the remote XT is shut down, the channels will go IDLE. Pressing live will load Cam A on both channels
- > Caps Lock functions like if the shift key is on (Bug ID 4736)
- > Retrimming clip in IP Director only affect the IP Director, not the Remote operator and vice-versa (Bug ID 6651)
- > When editing a playlist, the duration of all playlists in the playlist screen is temporarily affected (they are calculated like in cut mode) (Bug ID 5333)
- > On the SDTI Network, if a network cable is removed from a slave XHub where no server is connected, the master XHub can temporarily disconnect the XHub slave, causing a network disruption
- > VDCP protocol cannot be set as a secondary control of a remote. A command line parameter has to be used (RmtVdcpEx) if users want to use it in exclusive mode

## BEFORE 08.04

- > Timeline should not be used on XT1 – risks of audio problems in some configurations
- > Internal loop: in audio embedded, you always get the embedded audio, whether the loop mode is set to video+audio or video only.
- > Timeline limitations
  - Inserts and extends are in overwrite mode only
  - 3 points edits only.
  - It is necessary to have minimum two outputs
  - When the playlist is converted into a timeline, all videos and audio transitions are set to cut only
  - All video and audio transitions inside a timeline are cut only
  - The speed is always 100%
  - The duration of the timeline cannot be modified
  - The timeline feature is only available to the first remote of an XT server
- > In Playlist mode on the first PGM of the first remote if the Aux Track Parameter is set to PGM, when no aux clip is defined for the current playlist, the audio is not automatically replaced by the playlist's original audio. This is not a bug. The setting "Aux track to PGM" should only be used when an aux track is defined for the current playlist.
- > In interlace mode, IN and OUT points can only be marked on even field to avoid parity violation when chaining clips. If the operator marks an IN/OUT point on an odd field, the LSM will actually mark it to the next/previous even field, and jump to this field. In progressive mode, IN and OUT points can be marked on all fields.

- > When playing a playlist, Next, Skip not accepted during transition effects, or if the next transition is a split audio (different audio and video IN point, or different video and audio effect durations).
- > F7 to test mix/wipe effects in setup not yet implemented.
- > When adjusting YUV parameters to define a custom colour for wipe border, the corresponding colour is not displayed on main output.
- > Impossible to switch to another camera while searching with the jog. Stop jogging, switch to the new camera, then start jogging again.
- > On remote record trains, it is not possible to switch to another camera in play on the same PGM : the new camera will always appear in pause
- > Live on remote record trains is about 2-3 sec behind the actual live
- > Playlists of Page 10 are not available from the EVS remote because they are dedicated to the other RS422 protocols
- > The internal loop mode is not available with Super Motion configurations
- > To be able to rename or delete remote clips, the parameter "Clip Edit by Network" must be set to "Enable" on the server where the clip is stored
- > The keyword file must be distributed to all systems on a network by the Network Server. However, if this machine is disconnected for any reason, another server will automatically be designated as Network Server and will now be in charge of distributing the keyword file. If the "old" Network Server is reconnected to the network but does not recover automatically its Network Server status, the machine acting as the current Network Server must be disconnected in order to allow the "old" one to take back that job and distribute the keyword file again. This will be resolved in a future version by allowing a system not acting as Network Server to distribute keyword files as well
- > Resetting the "Protect Clip Pages" parameter in the setup does not reset the protect status of existing clips
- > It is not possible to flag a clip for archive before it is created
- > Setup Screen (Shift+F2) : the number of local and network clips is only refreshed when entering the screen
- > Delay Screen (Shift+F7) : when working in NTSC NDF mode, the time codes in this screen are still calculated on a DF basis
- > In Playlist Edit mode, copying a playlist exits that mode to return to live mode
- > Clearing the clips from the EVS menu, clears also the record trains and the camera names
- > The phase field in the configuration screen is not editable. Phase must be defined with the corresponding option in the maintenance menu

## COMPATIBILITY

### HARDWARE

- > **H3X board is only compatible with V3X video board, CODA 75 audio board and SAS drives**
- > **V3X compatible with H3X are NOT compatible with HCTX**
- > **CODA 75 is only compatible with H3X, NOT with HCTX**
- > **MTPC rev A3/A5 with HS873 is only compatible with Multicam 11.00.71 and above**
- > **Multicam 11 is only compatible with CODA 65 or CODA 75 audio boards**
- > Multicam 11 requires 128 MB of RAM on the MTPC board
- > The MTPC board must be A2/A4 or greater. Any other MTPC board will not be supported
- > USB keyboard is supported since Multicam 11.02
- > SAS drives are supported since Multicam 10.01.73
  - > Only SAS drives provided by EVS are supported
- > SCSI disks remain supported on the XT[2] and XS. For emergency support purposes, it is possible to use SCSI disks on XT[2]+, contact EVS support if you wish to do so
- > SCSI and SAS drives cannot be used simultaneously on the same server
- > This version is only compatible with XT3, XT[2], XT[2]+, XTnano, XL[2], XS and XSnano chassis and corresponding audio codecs
- > The HCT-X or H3X board must be equipped with the SDTI chipset to be able to use network options
- > This version is not compatible with HCT-2, HCT-4, HCT-S or XT1 chassis
- > The STXX Jumper on the backplane must be removed!

## XNET

- > SDTI Network in Multicam 11.02.87 is only compatible with 11.02.68 and above. It is not compatible with ANY OTHER lower version
- > Multicam 11.02.87 is only compatible with V3.03 and above of the XHub
- > If you need to upgrade the hub, please contact EVS to get the upgrade software and procedure
- > If unsure, you can check the version with the following procedure for XHub2:
  - o Turn off the hub
  - o Move all 4 dip switches on the front panel to the lower position
  - o Turn on the hub
  - o The 7 branch status LEDs will light according to a binary pattern, as described in the following below

Branch LED #	1	2	3	4	5	6	7
v. 1.06		green	red		green	green	
v. 1.07		green	red		green	green	green
v. 2.03	green		red			green	green
v. 2.04	green		red		green		
v. 2.05	green		red		green		green
v. 2.06	green		red		green	green	
v. 3.01	green	green	red				green
v. 3.03	green	green	red			green	green

- o Turn off the hub
- o Move all 4 dip switches back to the upper position

- > Or with the following procedure for XHub3:
  - Move up the version switch  
(This does not require switching off the XHub and it maintains normal operations during the version check)
  - The branch status LEDs show the software version in a binary pattern

Branch LED #	1	2	3	4	5	6	7	8
v. 3.03		green	green	red			green	green
v. 3.04		green	green	red		green		
v. 4.00	green			red				

- To return to normal LED behavior, move down the version switch

## CLIPS

- > A clear clip (clearing the video disks content) is mandatory switching from/to any version older than Multicam 9
- > Clips are kept switching from Multicam 9 and later to Multicam 11.02 and vice-versa
- > Playlists may be kept but without guarantee

## HYPERMOTION VISION RESERACH CAMERA

- > Multicam has been validated with Vision Research firmwares 758 and 763