

## CPU-ETH3 BASIC / STANDARD / ADVANCED

(DENSITE 3+ FR4)

### Release History

| Upgrade Package       | Comprising:      |                  | Release Date | User Manual for this release (Grass Valley document #) |
|-----------------------|------------------|------------------|--------------|--------------------------------------------------------|
|                       | Firmware Version | Software Version |              |                                                        |
| <a href="#">1.3.7</a> | 1.3.7.703        | NA               | 2018-12-18   | 3007-99M00-104                                         |
| <a href="#">1.3.5</a> | 1.3.5.702        | NA               | 2018-05-24   | 3007-99M00-104                                         |
| <a href="#">1.3.4</a> | 1.3.4.692        | NA               | 2018-01-15   | 3007-99M00-101                                         |
| <a href="#">1.3.3</a> | 1.3.3.684        | NA               | 2017-07-13   | 3007-99M00-101                                         |
| <a href="#">1.3.1</a> | 1.3.1.675        | NA               | 2017-03-07   | 3007-99M00-101                                         |

**NOTES:** The iControl compatibilities shown below are officially supported by Grass Valley. Earlier versions may also work, with bugs or limited features.

The Reference number (Ref#) given for each feature or bug in these Release Notes refers to internal Grass Valley documentation.

## UPGRADE PACKAGE: 1.3.7

Firmware version: [1.3.7.703](#)

Release date: [2018-12-18](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## ENHANCEMENTS & NEW FEATURES

| Ref #    | Description                        |
|----------|------------------------------------|
| CPU3-997 | Support for Armada 385 revision B0 |

## BUGS FIXED IN THIS RELEASE

| Ref # | Description |
|-------|-------------|
|       |             |

## KNOWN BUGS & LIMITATIONS

| Ref #                    | Description                                                                                                                                                              |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CPU3-917                 | <b>CPU-ETH3 assembly 3034-0100-503 cannot be downgraded below v1.3.0</b><br>Following message will be displayed during downgrade: "Cannot downgrade below version 1.3.0" |
| <a href="#">CPU3-62</a>  | <b>DHCP client not implemented</b>                                                                                                                                       |
| <a href="#">CPU3-510</a> | <b>Broken compatibility with RCP-10x0</b><br>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3).    |

---

|                          |                                                                                                                                                                                                                                              |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-515</a> | <p><b>Broken compatibility with SSP-3801</b></p> <p>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3).</p> <p>VERSIONS AFFECTED: versions earlier than 1.6.0</p> <p>WORKAROUND: Get a firmware update on SSP-3801.</p> |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

## UPGRADE PACKAGE: 1.3.5

Firmware version: [1.3.5.702](#)

Release date: [2018-05-24](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## ENHANCEMENTS & NEW FEATURES

| Ref #                    | Description                                                             |
|--------------------------|-------------------------------------------------------------------------|
| <a href="#">CPU3-979</a> | Introduction of the support of DENSITE 3+ FR4 Standard Frame Controller |

## BUGS FIXED IN THIS RELEASE

| Ref #                    | Description                                                               |
|--------------------------|---------------------------------------------------------------------------|
| <a href="#">CPU3-985</a> | LCD freezes<br>LCD process crashes and the LCD panel becomes unresponsive |

## KNOWN BUGS & LIMITATIONS

| Ref #                    | Description                                                                                                                                                              |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CPU3-917                 | <b>CPU-ETH3 assembly 3034-0100-503 cannot be downgraded below v1.3.0</b><br>Following message will be displayed during downgrade: "Cannot downgrade below version 1.3.0" |
| <a href="#">CPU3-62</a>  | <b>DHCP client not implemented</b>                                                                                                                                       |
| <a href="#">CPU3-510</a> | <b>Broken compatibility with RCP-10x0</b><br>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3).    |

---

|                          |                                                                                                                                                                                                                                              |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-515</a> | <p><b>Broken compatibility with SSP-3801</b></p> <p>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3).</p> <p>VERSIONS AFFECTED: versions earlier than 1.6.0</p> <p>WORKAROUND: Get a firmware update on SSP-3801.</p> |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

## UPGRADE PACKAGE: 1.3.4

Firmware version: [1.3.4.692](#)

Release date: [2018-01-15](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## ENHANCEMENTS & NEW FEATURES

| Ref #    | Description                                                                                                                                                            |
|----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CPU3-959 | <b>Fixed real time clock</b><br>Since version 1.3.0 the real time clock was not working correctly. Also, the real time clock was not correctly updated when using NTP. |

## KNOWN BUGS & LIMITATIONS

| Ref #                    | Description                                                                                                                                                                                                                   |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CPU3-917                 | <b>CPU-ETH3 assembly 3034-0100-503 cannot be downgraded below v1.3.0</b><br>Following message will be displayed during downgrade: "Cannot downgrade below version 1.3.0"                                                      |
| <a href="#">CPU3-62</a>  | <b>DHCP client not implemented</b>                                                                                                                                                                                            |
| <a href="#">CPU3-510</a> | <b>Broken compatibility with RCP-10x0</b><br>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3).                                                         |
| <a href="#">CPU3-515</a> | <b>Broken compatibility with SSP-3801</b><br>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3).<br><br>VERSIONS AFFECTED: versions earlier than 1.6.0<br>WORKAROUND: Get a firmware update on SSP-3801. |

## UPGRADE PACKAGE: 1.3.3

Firmware version: [1.3.3.684](#)

Release date: [2017-07-13](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## ENHANCEMENTS & NEW FEATURES

| Ref #                    | Description                                               |
|--------------------------|-----------------------------------------------------------|
| <a href="#">CPU3-949</a> | Added PTP statuses to « Reference Information » web page. |

## KNOWN BUGS & LIMITATIONS

| Ref #                    | Description                                                                                                                                                                                                                   |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CPU3-917                 | <b>CPU-ETH3 assembly 3034-0100-503 cannot be downgraded below v1.3.0</b><br>Following message will be displayed during downgrade: "Cannot downgrade below version 1.3.0"                                                      |
| <a href="#">CPU3-62</a>  | <b>DHCP client not implemented</b>                                                                                                                                                                                            |
| <a href="#">CPU3-510</a> | <b>Broken compatibility with RCP-10x0</b><br>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3).                                                         |
| <a href="#">CPU3-515</a> | <b>Broken compatibility with SSP-3801</b><br>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3).<br><br>VERSIONS AFFECTED: versions earlier than 1.6.0<br>WORKAROUND: Get a firmware update on SSP-3801. |

## UPGRADE PACKAGE: 1.3.1

Firmware version: [1.3.1.675](#)

Release date: [2017-03-07](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## BUGS FIXED IN THIS RELEASE

| Ref #                    | Description                                                                                  |
|--------------------------|----------------------------------------------------------------------------------------------|
| <a href="#">CPU3-893</a> | Saving restore point from card edge menu fails and causes a card reset in a GV Node chassis. |

## KNOWN BUGS & LIMITATIONS

| Ref #                    | Description                                                                                                                                                                                                                   |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CPU3-917                 | <b>CPU-ETH3 assembly 3034-0100-503 cannot be downgraded below v1.3.0</b><br>Following message will be displayed during downgrade: "Cannot downgrade below version 1.3.0"                                                      |
| <a href="#">CPU3-62</a>  | DHCP client not implemented                                                                                                                                                                                                   |
| <a href="#">CPU3-510</a> | <b>Broken compatibility with RCP-10x0</b><br>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3).                                                         |
| <a href="#">CPU3-515</a> | <b>Broken compatibility with SSP-3801</b><br>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3).<br><br>VERSIONS AFFECTED: versions earlier than 1.6.0<br>WORKAROUND: Get a firmware update on SSP-3801. |



## UPGRADE PACKAGE: 1.3.0

Firmware version: [1.3.0.672](#)

Release date: [2016-12-12](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## ENHANCEMENTS & NEW FEATURES

| Ref #                    | Description                                                                                                                                                                                                                                                                                                           |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-824</a> | Network link redundancy option can now be activated through the LCD menu                                                                                                                                                                                                                                              |
| <a href="#">CPU3-830</a> | <b>The controller now allows 10 free client connections</b><br>By default, there are N software clients that can connect to the controller. If additional clients want a connection, they need to specifically request it. Thus the first N clients get a “free” connection. The number N has now been changed to 10. |
| <a href="#">CPU3-41</a>  | <b>Changing Network settings does NOT trigger an automatic reboot</b><br>In previous releases, the controller would reboot automatically after changing Network settings.                                                                                                                                             |

## BUGS FIXED IN THIS RELEASE

| Ref #                    | Description                                            |
|--------------------------|--------------------------------------------------------|
| <a href="#">CPU3-734</a> | Sometimes at power-up, the network interfaces are down |

## KNOWN BUGS & LIMITATIONS

| Ref #                   | Description                 |
|-------------------------|-----------------------------|
| <a href="#">CPU3-62</a> | DHCP client not implemented |

---

|                          |                                                                                                                                                                                                                                                                       |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-510</a> | <b>Broken compatibility with RCP-10x0</b><br>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.                                                         |
| <a href="#">CPU3-515</a> | <b>Broken compatibility with SSP-3801</b><br>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.<br><br>VERSIONS AFFECTED: versions earlier than 1.6.0<br>WORKAROUND: Get a firmware update on SSP-3801. |

## UPGRADE PACKAGE: 1.0.5

Firmware version: [1.0.5.594](#)

Release date: [2016-06-14](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## ENHANCEMENTS & NEW FEATURES

| Ref #                    | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-63</a>  | <b>Implementation of the HOME screen on the LCD display</b><br>The HOME screen of the LCD gives an overall status of the frame. This includes an overall status of each card in the frame. The NAVIGATION menu of a particular card can be accessed by touching its associated button in the HOME screen.                                                                                                                                                                                                                                                                        |
| <a href="#">CPU3-64</a>  | <b>Implement network link redundancy option</b><br>This is the same feature as for the Densite 3 frame. When this option is purchased, the two control network interfaces work as a redundant pair. See user manual for details.                                                                                                                                                                                                                                                                                                                                                 |
| <a href="#">CPU3-339</a> | <b>Implement basic SNMP agent</b><br>This is the same feature as for the Densite 3 frame.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| <a href="#">CPU3-499</a> | <b>Changed default IP addresses</b><br>The new default IP addresses for the control ports are 192.168.3.3 and 192.168.4.3.                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| <a href="#">CPU3-577</a> | <b>The "Connections" web page has an improved status description</b><br>As described in the "Help" section of that web page, a new yellow widget was added to more accurately represent the status of Densite connections. The yellow status tells the user that certain type of data (either RAW or non-solicited) are not transferred because the maximum number of legacy connections has been reached. A legacy connection from a Densite client (eg. iControl) is a connection that does NOT specifically ask for those particular type of data (RAW and/or non-solicited). |

## BUGS FIXED IN THIS RELEASE

| Ref #                    | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-589</a> | <p><b>Clicking the "CTRL EXECUTION" item of the local menu locks and reboots immediately</b></p> <p>Once the user accesses this menu item, the card immediately locks up and eventually reboots without the user's confirmation to do so.</p>                                                                                                                                                                                                                                                          |
| <a href="#">CPU3-511</a> | <p><b>Broken compatibility with KMV-3911 and KMV-3901</b></p> <p><b>NOTE:</b> Fixed with update of KMV to version 8.10.</p> <p>These cards are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames. The problem occurs only when the cards are inserted in slots 21 to 24 of the FR4 frame. In these cases, they are not displaying on the LCD screen once the attention button is pressed.</p> <p>VERSIONS AFFECTED: for both, version 7.91 and lower</p> |
| <a href="#">CPU3-516</a> | <p><b>Broken compatibility with Kaleido-Modular-X series (KMX)</b></p> <p><b>NOTE:</b> Fixed with update of KMX to version 8.00.</p> <p>The KMX Multiviewer cards are incompatible with the new Densite controller (CPU-ETH3).</p> <p>VERSIONS AFFECTED:</p> <ul style="list-style-type: none"> <li>The KMX-3901-IN cards (all flavors) running KXS version below 8.00 are not compatible.</li> <li>The KMX-3901-OUT card is NOT affected.</li> </ul>                                                  |
| <a href="#">CPU3-676</a> | <p><b>"Reference Information" web page returns cryptic error message (ACK 4272)</b></p> <p>This issue can happen if the card is currently being upgraded or if it is stuck in its bootloader (failed upgrade). The message displayed in the "Reference Information" web page is :</p> <p><b>ERROR: failed to received ACK 4272</b></p>                                                                                                                                                                 |
| <a href="#">CPU3-699</a> | <p><b>Cannot control a KMX-4911 using the NP0016 protocol</b></p> <p>Using the network port of the frame controller, the KMX-4911 cards should be controllable via the NP0016 protocol (routing protocol)</p>                                                                                                                                                                                                                                                                                          |
| <a href="#">CPU3-718</a> | <p><b>Sometimes after a power cycle of the frame, cards are not accessible through the LCD screen</b></p>                                                                                                                                                                                                                                                                                                                                                                                              |

---

## KNOWN BUGS & LIMITATIONS

| Ref #                    | Description                                                                                                                                                                                                                                                           |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-62</a>  | DHCP client not implemented                                                                                                                                                                                                                                           |
| <a href="#">CPU3-510</a> | <b>Broken compatibility with RCP-10x0</b><br>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.                                                         |
| <a href="#">CPU3-515</a> | <b>Broken compatibility with SSP-3801</b><br>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.<br><br>VERSIONS AFFECTED: versions earlier than 1.6.0<br>WORKAROUND: Get a firmware update on SSP-3801. |

## UPGRADE PACKAGE: 1.0.3

Firmware version: [1.0.3.530](#)

Release date: [2016-02-19](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## BUGS FIXED IN THIS RELEASE

| Ref #                    | Description                                                                                                                                                                                                                                                                                                                                                                                                            |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-543</a> | <b>A card 5 slots down from a card being initialized no longer communicates with CPU-ETH3</b><br>If a card is re-initialized by simply re-inserting the card or other means, it may prohibit another card, 5 slots down in the frame, to communicate with the CPU-ETH3.                                                                                                                                                |
| <a href="#">CPU3-526</a> | <b>Minimize accesses to SD card</b><br>Minimize wear of SD card.                                                                                                                                                                                                                                                                                                                                                       |
| <a href="#">CPU3-518</a> | <b>Detect and correct SD card corruption on power-up</b><br>Make fsck run non-interactively at boot time when errors are detected on the file system.                                                                                                                                                                                                                                                                  |
| <a href="#">CPU3-527</a> | <b>Detect when file system is remounted read-only because of file system corruption</b><br>Detect if the file system (/config and /data) gets remounted as read-only when a corruption occurs. When detecting the file system is now read-only, notify user as follows: <ul style="list-style-type: none"> <li>• Set LED red</li> <li>• Write event to Log</li> <li>• Display in local LCD menu (in status)</li> </ul> |
| <a href="#">CPU3-551</a> | <b>Use md5 to detect file corruptions on the SD card during upgrade</b><br>Use md5 check to make sure the files in the new file system are not corrupted before switching partition.                                                                                                                                                                                                                                   |
| <a href="#">CPU3-297</a> | <b>Low-level bootloader (u-boot) updated to meet hardware specifications</b>                                                                                                                                                                                                                                                                                                                                           |

## KNOWN BUGS & LIMITATIONS

| Ref #                    | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-63</a>  | <p><b>Home screen : all board status summary</b></p> <p>Missing status of all cards' LED on the LCD display.</p> <p>WORKAROUND: Open the frame door to see the card status.</p>                                                                                                                                                                                                                                                                                                                                                    |
| <a href="#">CPU3-64</a>  | <p><b>Optional full network link redundancy using channel bonding</b></p> <p>The network link will not automatically switch over the secondary physical port in case of failure of the primary port.</p>                                                                                                                                                                                                                                                                                                                           |
| <a href="#">CPU3-339</a> | <p><b>SNMP agent not implemented</b></p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| <a href="#">CPU3-62</a>  | <p><b>DHCP client not implemented</b></p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
| <a href="#">CPU3-510</a> | <p><b>Broken compatibility with RCP-10x0</b></p> <p>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.</p>                                                                                                                                                                                                                                                                                                           |
| <a href="#">CPU3-515</a> | <p><b>Broken compatibility with SSP-3801</b></p> <p>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.</p> <p>VERSIONS AFFECTED: versions earlier than 1.6.0</p> <p>WORKAROUND:</p> <ul style="list-style-type: none"> <li>Get a firmware update on SSP-3801.</li> </ul>                                                                                                                                                                                             |
| <a href="#">CPU3-516</a> | <p><b>Broken compatibility with Kaleido-Modular-X series (KMX)</b></p> <p>The KMX Multiviewer cards are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.</p> <p>VERSIONS AFFECTED:</p> <ul style="list-style-type: none"> <li>The KMX-3901-IN cards (all flavors) running KXS version below 8.00 are not compatible.</li> <li>The KMX-3901-OUT card is NOT affected.</li> </ul> <p>WORKAROUND:</p> <ul style="list-style-type: none"> <li>Upgrade to KXS 8.00 or newer.</li> </ul> |
| <a href="#">CPU3-511</a> | <p><b>Broken compatibility with KMV-3911 and KMV-3901</b></p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |

---

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                          | <p>These cards are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames. The problem occurs only when the cards are inserted in slots 21 to 24 of the FR4 frame. In these cases, they are not displaying on the LCD screen once the attention button is pressed.</p> <p>VERSIONS AFFECTED: for both, version 7.91 and lower</p> <p>WORKAROUND:</p> <ul style="list-style-type: none"><li>• Upgrade firmware of those cards.</li></ul> |
| <a href="#">CPU3-589</a> | <p><b>Clicking on the "CTRL EXECUTION" card edge menu item locks up the card and reboot</b></p> <p>Once the user accesses this menu item, the card immediately locks up. It then eventually reboots without the user's confirmation to do so.</p>                                                                                                                                                                                                                                |



## UPGRADE PACKAGE: 1.0.2

Firmware version: [1.0.2.512](#)

Release date: [2015-12-22](#)

iControl compatibility: [7.10+](#)

iControl Solo compatibility: [7.10+](#)

RCP-200 compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies.](#)

## ENHANCEMENTS & NEW FEATURES

| Ref #                   | Description                                                                                                                                                     |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-67</a> | <b>Initial PUBLIC release of the “basic” CPU-ETH3 for the FR4 frame</b><br>This is the first official version available for production of the “basic” CPU-ETH3. |

## KNOWN BUGS & LIMITATIONS

| Ref #                    | Description                                                                                                                                                                                                   |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-63</a>  | <b>Home screen : all board status summary</b><br>Missing status of all cards' LED on the LCD display.<br><br>WORKAROUND: Open the frame door to see the card status.                                          |
| <a href="#">CPU3-64</a>  | <b>Optional full network link redundancy using channel bonding</b><br>The network link will not automatically switch over the secondary physical port in case of failure of the primary port.                 |
| <a href="#">CPU3-339</a> | <b>SNMP agent not implemented</b>                                                                                                                                                                             |
| <a href="#">CPU3-62</a>  | <b>DHCP client not implemented</b>                                                                                                                                                                            |
| <a href="#">CPU3-510</a> | <b>Broken compatibility with RCP-10x0</b><br>The control Panel RCP-1010, RCP-1020, RCP-1030 and RCP-1040 are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames. |

|                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CPU3-515</a> | <p><b>Broken compatibility with SSP-3801</b></p> <p>The SSP-3801 is incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.</p> <p>VERSIONS AFFECTED: versions earlier than 1.6.0</p> <p>WORKAROUND:</p> <ul style="list-style-type: none"> <li>Get a firmware update on SSP-3801.</li> </ul>                                                                                                                                                                                                         |
| <a href="#">CPU3-516</a> | <p><b>Broken compatibility with Kaleido-Modular-X series (KMX)</b></p> <p>The KMX Multiviewer cards are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames.</p> <p>VERSIONS AFFECTED:</p> <ul style="list-style-type: none"> <li>The KMX-3901-IN cards (all flavors) running KXS version below 8.00 are not compatible.</li> <li>The KMX-3901-OUT card is NOT affected.</li> </ul> <p>WORKAROUND:</p> <ul style="list-style-type: none"> <li>Upgrade to KXS 8.00 or newer.</li> </ul>             |
| <a href="#">CPU3-511</a> | <p><b>Broken compatibility with KMV-3911 and KMV-3901</b></p> <p>These cards are incompatible with the new Densite controller (CPU-ETH3) found in the FR4 and the GV Node frames. The problem occurs only when the cards are inserted in slots 21 to 24 of the FR4 frame. In these cases, they are not displaying on the LCD screen once the attention button is pressed.</p> <p>VERSIONS AFFECTED: for both, version 7.91 and lower</p> <p>WORKAROUND:</p> <ul style="list-style-type: none"> <li>Upgrade firmware of those cards.</li> </ul> |