

HCP-1801 – Upgrade Package 2.1.1

UPGRADE PACKAGE RELEASE HISTORY

Release Version	Comprising:		Deleges Deta	Version	User Manual for this
	Firmware Version	Software Version	Release Date	Details	release (Grass Valley document #)
2.1.1	2.1.9	2.1.1	2014.06.20	<u>(go)</u>	M813-9900-111

NOTES: The iControl compatibilities shown below are officially supported by Grass Valley. Earlier versions may also work, with bugs or limited features.

The Reference number (Ref#) given for each feature or bug in these Release Notes refers to internal Grass Valley documentation.



UPGRADE PACKAGE: 2.1.1

Release date: 2014-06-20

iControl compatibility: 5.0 and later

iControl Solo compatibility: 5.0 and later RCP-200 compatibility: Not supported

Hardware compatibility: This upgrade package applies to all existing hardware assemblies.

ENHANCEMENTS & NEW FEATURES

Ref#	Description

BUGS FIXED IN THIS RELEASE

Ref #	Description	
001-00- 015485	The CC validity, Closed Captions and WST "duration" values do not persist When restarting the card, the duration parameter for the above probes is restored to its default value of 10 (instead of keep the last value set before the restart of the card).	
001-00- 015548	HCP ALMs do not update when AES1 or AES2 is killed in group 1 The card cannot handle an invalid or unlocked AES in an audio group. If one of the 2 AES of an audio group is "unlocked", the entire group is detected as invalid.	

Ref #	Description
001-00- 015485	The CC validity, Closed Captions and WST "duration" values are not saved in user presets These parameters are excluded from the card's user presets. Thus Restoring a preset does not affect their current value.

grass valley A BELDEN BRAND

Release Notes

PREVIOUS RELEASES

FIRMWARE VERSION: 218

Release date: 2013-01-21

iControl compatibility: v4.40 and up

iControl Solo compatibility: NA (will need a Solo 3.52)

RCP-200 compatibility: Not supported

Hardware compatibility: This firmware applies to all existing hardware assembly.

ENHANCEMENTS & NEW FEATURES

Ref#	Description
00001	Addition of AFD in SD formats The AFD flags can now be detected and extracted in both 525 lines 59.94Hz and 625 lines 50 Hz formats as it is with the 720p and 1080i video format signals. Furthermore, the support of some missing AFD codes have also been added to this release

BUGS FIXED IN THIS RELEASE

Ref#	Description

Ref#	Description



FIRMWARE VERSION: 217

Release date: 2011-10-11

iControl compatibility: 3.52 build 52 iControl Solo compatibility: 3.52

RCP-200 compatibility: Not supported

Hardware compatibility: This firmware applies to all existing hardware assemblies.

ENHANCEMENTS & NEW FEATURES

Ref#	Description

BUGS FIXED IN THIS RELEASE

Ref#	Description
	When submit to many video transition upstream while using the thumbnail, the card might stop responding to the Densite controller and/or disappear from iControl.
001-00- 005982	When the thumbnail streaming is activated while the input video stream sent to the card is « unstable », the card might stop communicating with the controller for a certain time. This behavior is random and might occur only on some cards. When in this state, the card can recover from itself but the time to recover is also random and can be from few minutes to some days. A reseating of the card into the frame correct this problem immediately.

Ref#	Description



FIRMWARE VERSION: 216

Release date: 2011-06-01

iControl compatibility: 3.52 (build 0052)

iControl Solo compatibility: 3.52

RCP-200 compatibility: Not supported

Hardware compatibility: This firmware applies to all existing hardware assembly.

ENHANCEMENTS & NEW FEATURES

Ref#	Description

BUGS FIXED IN THIS RELEASE

Ref#	Description
	HCP-1801 Video and Audio probing does not work properly after a copy profile or a load user preset
<u>001-00-</u> <u>005049</u>	When the current profile is updated using a file with the "Copy Profile" function in iControl, the card might not behave as expected for the audio and video probing. The GUI displays all the expected configuration parameters but the card might NOT behave according to this parameters.

Ref#	Description



FIRMWARE VERSION: 209

Release date: 2011-03-15

iControl compatibility: 3.52 (build 0052)

iControl Solo compatibility: 3.52

RCP-200 compatibility: Not supported

Hardware compatibility: This firmware applies to all existing hardware assembly.

ENHANCEMENTS & NEW FEATURES

Ref#	Description
	NCO for a Radio-Canada project : HCP-1801 + SCO-1421 + GPI-1501
<u>001-00-</u> <u>004596</u>	New feature developed for Radio-Canada (Montreal). This is implemented as an NCO ("ANC"), thus not publicly available to other customers.
	The card sends a message to an associated GPI-1501 card to trigger GPI-OUT based on certain alarms.

BUGS FIXED IN THIS RELEASE

Ref#	Description

Ref#	Description



FIRMWARE VERSION: 208

Release date: 2009-11-12

iControl compatibility: 3.52 (build 0052)

iControl Solo compatibility: 3.52

RCP-200 compatibility: Not supported

Hardware compatibility: This firmware applies to all existing hardware assembly.

ENHANCEMENTS & NEW FEATURES

Ref#	Description

BUGS FIXED IN THIS RELEASE

Ref#	Description
2009-	Mismatch in the time shown by the 7 days viewer iControl no longer tries to match message count with appserver time, because
00207	appserver time is not precise enough.
2009-	The 7 days viewer is only available on one card at a time
00292	In iControl, the support of several cards is not supported.
2009-	Mismatch in the reported error of the MBD viewer
	In the iControl log file, there are no more bad values recorded.
1234- 0001	VBI data analysis malfunction
	In some cases, the VBI data extraction and detection (like Close Captioning, Time Code or Video line Index) was not working properly.



1234- 0002	Freeze detection problem with the 720p video format
	The freeze detection was not working properly in 720p format and with some specific window size only.
1234- 0003	Services of HD Close Captioning error toggling
	With various video feeds, the iControl LED that reported the absence of the HD services of the CC was toggling regularly from GREEN to RED due to the CC insertion method. With this release, the service presence must now have disappeared for at least 5 seconds for the user to be notified of it.
1234- 0004	Video probing parameter mismatch
	Upon video input format change, some video probing parameters was not update properly.

Ref#	Description