



# **KAYENNE**

## VIDEO PRODUCTION CENTER

Release Notes Addendum  
Software Version 3.0.1

# Contacting Grass Valley

<b>International Support Centers</b>	<b>France 24 x 7</b>	+800 8080 2020 or +33 1 48 25 20 20	<b>United States/Canada 24 x 7</b>	+1 800 547 8949 or +1 530 478 4148
<b>Local Support Centers (available during normal business hours)</b>	<b>Asia</b>	<b>Hong Kong, Taiwan, Korea, Macau:</b> +852 2531 3058 <b>Indian Subcontinent:</b> +91 22 24933476 <b>Southeast Asia/Malaysia:</b> +603 7805 3884 <b>Southeast Asia/Singapore:</b> +65 6379 1313 <b>China:</b> +861 0660 159 450 <b>Japan:</b> +81 3 5484 6868		
		<b>Australia and New Zealand:</b> +61 1300 721 495	<b>Central/South America:</b> +55 11 5509 3443	
		<b>Middle East:</b> +971 4 299 64 40 <b>Near East and Africa:</b> +800 8080 2020 or +33 1 48 25 20 20		
	<b>Europe</b>	<b>Belarus, Russia, Tadzikistan, Ukraine, Uzbekistan:</b> +7 095 2580924 225 <b>Switzerland:</b> +41 1 487 80 02 <b>S. Europe/Italy-Roma:</b> +39 06 87 20 35 28 <b>-Milan:</b> +39 02 48 41 46 58 <b>S. Europe/Spain:</b> +34 91 512 03 50 <b>Benelux/Belgium:</b> +32 (0) 2 334 90 30 <b>Benelux/Netherlands:</b> +31 (0) 35 62 38 42 1 <b>N. Europe:</b> +45 45 96 88 70 <b>Germany, Austria, Eastern Europe:</b> +49 6150 104 444 <b>UK, Ireland, Israel:</b> +44 118 923 0499		

Copyright © Grass Valley USA, LLC. All rights reserved.

This product may be covered by one or more U.S. and foreign patents.

## Grass Valley Web Site

The [www.grassvalley.com](http://www.grassvalley.com) web site offers the following:

**Online User Documentation** — Current versions of product catalogs, brochures, data sheets, ordering guides, planning guides, manuals, and release notes in .pdf format can be downloaded.

**FAQ Database** — Solutions to problems and troubleshooting efforts can be found by searching our Frequently Asked Questions (FAQ) database.

**Software Downloads** — Download software updates, drivers, and patches.



## END-OF-LIFE PRODUCT RECYCLING NOTICE

Grass Valley's innovation and excellence in product design also extends to the programs we've established to manage the recycling of our products. Grass Valley has developed a comprehensive end-of-life product take back program for recycle or disposal of end-of-life products. Our program meets the requirements of the European Union's WEEE Directive, the United States Environmental Protection Agency, and U.S. state and local agencies.

Grass Valley's end-of-life product take back program assures proper disposal by use of Best Available Technology. This program accepts any Grass Valley branded equipment. Upon request, a Certificate of Recycling or a Certificate of Destruction, depending on the ultimate disposition of the product, can be sent to the requester.

Grass Valley will be responsible for all costs associated with recycling and disposal, including freight. However, you are responsible for the removal of the equipment from your facility and packing the equipment to make it ready for pickup.



For further information on the Grass Valley product take back system please contact Grass Valley at + 800 80 80 20 20 or +33 1 48 25 20 20 from most other countries. In the U.S. and Canada please call 800-547-8949, and ask to be connected to the EH&S Department. Additional information concerning the program can be found at: [www.grassvalley.com/about/environmental-policy](http://www.grassvalley.com/about/environmental-policy)

001187401

# Kayenne Release Notes Addendum

## Software Issues Resolved in 3.0.1

Table 1. Resolved Software Issues

Area	Issues	ID
Acquire Resources	Resource acquisition can force PGM A to output black in unusual circumstances.	35140
Acquire Resources	Automatic resource allocation sometimes fails when MEs are acquired, by loading Engineering Setups.	35141
Control Panel	Source selects and cuts are missed in random but rare circumstances.	38763
Corner Pinning	Corner Pinning should set corners to match crop when turned on.	38887
Devices Event List	Menu crashes upon entering Event List if no devices are configured.	35008
E-MEM & Timeline	Running E-MEMs while the Frame is still loading, in rare circumstances, can lock up the Frame.	28455
E-MEM & Timeline	Keyframe Hold on iDPM effect using E-MEM & Timeline Path Menu does not always work.	35153
E-MEM & Timeline	Recalling an effect on a Local ME while the Master Timeline is running, can cause a flash to Keyframe 1.	38816
Eng Setup	Loading Eng Setup when ClipStore is enabled disconnects the ClipStore's channels.	38097
File Ops	Loading or saving a show can hang with message "Waiting for response from frame...".	38160
File Ops	File Ops Clear and Replace button should default to off (located in File Ops, Show Files, Choose Load pane).	38883
Keyer	Chroma Key autoseup is not working in the Secondary partition.	34935
Local Aux Module	Aux Bus transitions become disabled on one part of the Local Aux Module.	38960
Local Aux Module	With some cabling configurations, the Local Aux Module can fail to initialize after rebooting the PCU.	38965
Local E-ME Module	Setting the dissolve rate on Local E-MEM Module sets the bank selection to zero.	40005
Macro Editor	Some macros stop working correctly after editing.	38902
Macro Editor	Inserting a comment into a macro using the Macro Editor causes the macro to stop at the comment line.	38923
Master E-MEM Module	Jog enable in Master E-MEM Module should default to off.	38882
Menu	Vertical bar entered from menu should be Unicode 00A6 not Unicode 007C.	34573
Menu	Menu double-tap interval is too long, impacting menus such as Timeline Edit and Timeline View.	39147

Table 1. Resolved Software Issues - (continued)

Area	Issues	ID
Menu	Some menus are slow and degrade further with prolonged use.	40764
Multi-Function Module	Copy Swap from Keyer to eDPM is not working when using the Multi-Function Module.	35306
Multi-Function Module	Multi-Function Module incorrectly reports the Frame address as "0.0.0.0", occasionally.	38609
Outputs	YUV Balance adjustment has opposite polarity on some Aux buses.	35056
Outputs	Unprotects are not being recognized when Encore is controlling Aux Buses.	35058
Panel Memory	Panel Memory can lock up the frame when recalled simultaneously from two panels in the same suite.	38561
SetDef	SetDef output color space conversion is incorrect when converting from HD to SD and from SD to HD.	38069
Suite Prefs	Bus Delegate and Shift buttons should default to the bus color.	35294
Switched Preview	Switched Preview does not return to correct ME after Chroma Key Auto Setup in some cases.	39514
Switcher Tally	DPMs when turned off can falsely tally Keys on-air.	38189
Switcher Tally	Serial tally includes DPM even when DPM is turned off. This can give false key-on indications in serial tally.	38857
Timeline Copy	Timeline copy to a target using ME50 can crash the frame.	40710
Transition Chaining	Background chains should always override flip-flops at the end of transitions.	34540
Transition Chaining	Pri/Sec Sync of background chains can be broken when menu changes secondary.	38190
Transition Module	Rapid lever arm movements in rare circumstances can be missed.	40692
Video Settings	Text is illegible in the Timing Analyzer menu display.	38653

## Known Software Issues

Table 2. Known Software Issues

Area	Issues	ID
File Ops	When saving files to an NTFS USB stick, the file permissions are being saved for user 'Everyone' which causes problems on some PCs. Workaround: Use Fat32 for USB stick, add 'Everyone' user to the PC, and change file permissions on the folders.	38070
File Ops	Cancelling a Show File update may result in files being erased from the show. Workaround: Verify the show contents after cancelling an update and if there are files missing, update the show again by pressing the Update Show button.	40743
Frame Status	Kayenne Menu does not report Video Frame power supply over temperature. Workaround: Power supply status is reported in web page and frame logs.	40925
Image Store	Image Store Library workflow results in folders being inaccessible by the Image Store. Workaround: When folders are transferred from Windows into the Images Folder make sure the folder Properties / Security / Advanced / Permissions "Inherit from parent the permission entries that apply to child objects." is checked.	38271

Table 2. Known Software Issues - (continued)

Area	Issues	ID
Image Store	The Image Store Backup and Restore does not work for folders with an underscore in the name. Workaround: Do not use an underscore in Image Store directory names.	39811
Image Store	The local aux panel incorrectly indicates an out of time source for re-entered sources to Image Store inputs (2,4,6).	106295
Image Store	Stills created in 720p are appearing as Movie files with 2 frames.	114339
Multi-Function Module	Fast Forward for devices is not being correctly initiated from the Positioner on the Multi-Function Module.	34938
Router Interface	Router destinations with unique names longer than 8 characters but not unique for the first 8 characters will have problems. (Standard nomenclature for current router environments is to have 8 characters or less.) Workaround: Router destinations and sources must be unique for the first 8 characters.	106188

