

K-FRAME VIDEO PRODUCTION CENTER

Release Notes Addendum

VERSION 15.1.0

13-00005-000-BC

2020-12-08

www.grassvalley.com

Patent Information

This product may be protected by one or more patents. For further information, please visit: www.grassvalley.com/patents/

Copyright and Trademark Notice

Grass Valley[®], GV[®] and the Grass Valley logo and/or any of the Grass Valley products listed in this document are trademarks or registered trademarks of GVBB Holdings SARL, Grass Valley USA, LLC, or one of its affiliates or subsidiaries. All other intellectual property rights are owned by GVBB Holdings SARL, Grass Valley USA, LLC, or one of its affiliates or subsidiaries. All third party intellectual property rights (including logos or icons) remain the property of their respective owners.

Copyright ©2018 GVBB Holdings SARL and Grass Valley USA, LLC. All rights reserved.

Specifications are subject to change without notice.

Terms and Conditions

Please read the following terms and conditions carefully. By using Video Production Center documentation, you agree to the following terms and conditions.

Grass Valley hereby grants permission and license to owners of Video Production Center to use their product manuals for their own internal business use. Manuals for Grass Valley products may not be reproduced or transmitted in any form or by any means, electronic or mechanical, including photocopying and recording, for any purpose unless specifically authorized in writing by Grass Valley.

A Grass Valley manual may have been revised to reflect changes made to the product during its manufacturing life. Thus, different versions of a manual may exist for any given product. Care should be taken to ensure that one obtains the proper manual version for a specific product serial number.

Information in this document is subject to change without notice and does not represent a commitment on the part of Grass Valley.

Warranty information is available from the Legal Terms and Conditions section of Grass Valley's website (www.grassvalley.com).

Recycling

Visit www.grassvalley.com for recycling information.

| Title | K-FRAME Release Notes Addendum |
|-------------|--------------------------------|
| Part Number | 13-00005-000-BC |
| Revision | 2020-12-04, 12:04 |

K-Frame Release Notes Addendum, V15.1.0

About this Manual

This document includes new features and "Resolved" and "Known" issues for K-Frame software version 15.1.0. See the K-Frame Release Notes, version 15.0 for Grass Valley Video Production Center software update instructions.

IMPORTANT: 15.1.0 is only supported by the GV K-Frame XP Compact Video Production Center.

For More Information

For information about installing, configuring, and operating K-Frame systems, see the K-Frame Video Production Center Documentation Libraries found on the Grass Valley website and on the USB thumb drive provided with your system.

Known Issues in Release 15.1.0

See Known Issues, on page 2.

Software Issues Resolved in Release 15.1.0

| Area | Issues | ID | Case ID |
|----------------------------|--|------------|---------|
| 2DPM | Moving 2DPM off-screen or shrinking to zero size should not tally as on-air. | KFCK-25527 | |
| Input Timing | The Input Timing Analyzer is not always correct for some I/O Boards. | KFCK-25526 | |
| Signal Integrity | Occasional minor bit errors on some signal paths. | KFCK-25914 | |
| Frame Operating Mode | 2160p 29.97 is set in the wrong color space. | KFCK-25909 | |
| E-MEM | The frame is giving next register instead of the next empty register to LEARN DOT (.) command for some register ranges. | KFCK-25911 | |
| Camera Tally | Camera Tally via XML Camera Protocol may not work for cameras without a base station or CCU. (This includes the LDX 100) | KFCK-24271 | |

| Area | Issues | ID | Case ID |
|--------------------------|--|------------|---------|
| Panel Memory | Panel Memory is not always being recalled from disk correctly in show loads or individually. | KFCK-25923 | |
| E-MEM & Timeline Menu | E-MEM & Timeline > Timeline Edit > E- MEM Enable for Keyers 5 and 6 are not visible. | KFCK-25926 | |

Known Issues

| Area | Issues | ID | Case ID |
|----------------|---|------------|----------|
| Input Timing | The Input Timing Analyzer is not always correct for some I/O Boards. | KFCK-25526 | |
| Clip Store | Using a Macro to stop a ClipStore recording leaves the channel in record mode. Stopping the recording by pressing the menu Stop button works correctly. Workaround: Do not use Macros to stop a recording or if you do, toggle the Record Enable button to get back into play mode. | KFCK-9060 | |
| Control Panel | On a few systems, when the Control Panel is reset, the video may perform a transition and the video may randomly cut to what is on the preview bus. | KFCK-21481 | 00604179 |
| Device Control | Devices at frame rates slower than 25Hz may not be controlled correctly. | KFCK-25543 | |
| Device Control | Sometimes after a reset of the frame, none of the devices (except the ClipStore) are enabled in suite 2. They can be enabled manually. | KFCK-24235 | |
| DPM | In a Standard Definition Frame Operating mode with a 16:9 aspect ratio, the default crops are incorrect. Workaround: Set the default DPM crops in Engineering Configuration to what looks appropriate on screen. | KFCK-24315 | 00618966 |
| E-MEM | Circular sequencing of registers is not supported. | KFCK-9965 | |

| Area | Issues | ID | Case ID |
|-------------------------------|---|------------|---------|
| Editor Interface | The first time an Editor Port is assigned, enabled and connected, it may not start correctly. WORKAROUND: If the Editor Port is configured to the desired state and does not work the first time, reset the Frame and Menu and enter the Editor Port configurations a second time. | KFCK-21673 | |
| GV K-Frame X: IP I/O Board | On rare occasion with some Cisco network switches with QSFP, after a boot, the input video may be pink or green. WORKAROUND: Reset the QSFP in the Cisco network switch. | KFCK-24858 | |
| GV Korona Control Panel | User Setup > Panel Prefs > Panel User Interactions > OLED brightness soft knob adjustment is not linear. If you are at 100% and take the brightness to 10%, you don't see the change until you turn the knob up again. | KFCK-19507 | |
| GV Korona Menu | GV Korona menu brightness doesn't work in User Setups > Panel Prefs > Panel User Interactions. Workaround: Set the menu brightness using Windows adjustments. | KFCK-19509 | |
| Hot Swap | During the hot swap of a Frame board, if another board is removed and replaced, the removal of the second board is not detected. Workaround: Wait ten seconds between hot swapping boards. | KFCK-17208 | |
| Image Store | After recording a movie, the blue progress bar may be blank until the movie is saved to cache. | KFCK-18178 | |
| IP I/O | Eng Setup, Video I/O, IP I/O Config, Inputs menu: IGMPv3 SSM fields should be grayed out as it is not supported at this time. | KFCK-25454 | |
| IP I/O Board | Hot swap of IP I/O board may affect adjacent IP I/O Board. | KFCK-25542 | |
| IP Video I/O | It takes over 30 seconds to change SFP Speed on IP cards; it will flash twice after the change is made. | KFCK-25182 | |

| Area | lssues | ID | Case ID |
|--|--|----------------------|----------|
| K-Frame X: PTP | Loss of the PTP messages might not be reported since the Flywheel Reference on the PTP Board is providing a valid reference that had been synchronous with the PTP Master Clock. | KFCK-25181 | |
| K-Frame X/ V-Series: IP I/O Timing Analyzer | When receiving a signal on a ST2110-20 stream, the timing analyzer reports that input as being the same as the Frame Operating Mode no matter what the format of the incoming stream. 2022-6 inputs may be reported incorrectly if they have Audio (ST 2110-30). | KFCK-23710 | |
| Karrera Control Panel | DPOP of USER buttons does not work if Split ME and PRI/SEC are selected. | KFCK-9332 | |
| Karrera Control Panel Memory | Panel Memory on the Karrera does not record the page offsets of the Macro Mode in the Local E-MEM section. | KFCK-8249 | |
| Kayenne Control Panel/Machine Control | Machine Control Module only works from Suite 1 Surface A and/or Suite 2 Surface A. | KFCK- 9933/DE364 | |
| Machine Control | Enabled devices that are not connected, will continue to try and connect which can cause menu slow-downs. Workaround: Disable unused devices. | KFCK- 9101/DE1228 | |
| Macro Edit/Build | Starting to edit or saving a macro may be delayed during a file operation in either suite. | KFCK- 8505/DE1831 | 00487254 |
| Media Port Input | Media Port on 8x4 SDI board detects 1080i when no video is connected. | KFCK-25170 | |
| Menu Software Installation | Immediately after the installation of new software, the Status Menu reports the previous version of the software even after a successful update.: Workaround: Restarting the Menu corrects the issue. | KFCK-19611 | |
| Node Settings | Joy Stick Override mapped to "None" still selects source 1. | KFCK-9953/ DE344 | |
| System Timing | Sometimes internal sources are incorrectly reported as out of time. | KFCK-24868 | 00695116 |
| Timing Analyzer | Color visual indicator missing on Redundant inputs. | KFCK-25545 | |



Grass Valley Technical Support

For technical assistance, contact our international support center, at 1-800-547-8949 (US and Canada) or +1 530 478 4148.

To obtain a local phone number for the support center nearest you, please consult the Contact Us section of Grass Valley's website (www.grassvalley.com).

An online form for e-mail contact is also available from the website.

Corporate Head Office

Grass Valley 3499 Douglas-B.-Floreani St-Laurent, Quebec H4S 2C6 Canada Telephone: +1 514 333 1772 Fax: +1 514 333 9828 www.grassvalley.com