# New Product Release – Package 8 XT[2] System and Software

19 Jan 2009

1.1	New Operational Features in Multicam 8	
1.2	New hardware features	
1.3	New System features	
1.4	BUG FIXES UP TO 08.04.33	
1.5	Known Issues	
1.6	LIMITATIONS	
1.7	CLIP COMPATIBILITY	<i>8</i>

# 1.1 New Operational Features in Multicam 8

# 1.1.1. Controller Set up Menu Items

## Page 2.2 : Record Trains



In default mode of 'No' this setting has no impact on the operation of the software.

When activated by selecting 'Yes' the video output of a channel when playing a record train will freeze at each cue point marked. This allows the output to be stopped at multiple places on playback.

Note: The setting chosen in Page 2.2 (F3) will determine whether the mark is made on the 'LIVE' train or on the playback of the train.

## Page 3.3 : Clips



This setting changes the function of the Browse button. In the default Browse mode, it will activate Browse.

If the assignment is changed to SORT-TC, the system will perform a SORT-TC.

**Note**: The system will not prompt the user with a menu to select the SORT criteria but will use the last settings selected in the soft menu SORT-TC , and use the current TC of the selected output channel.

To perform a search with different criteria (Search Net or Local, StartDate, EndDate, CAM/CLIP, etc...) the user should use the normal soft menu Sort-TC.

## Page 3.4 : TimeLine



The Receive Page setting selects where clips that are created as part of the timeline editing process will be stored.

The Mono Per Track setting determines how the audio tracks are grouped for editing using the timeline feature.

## Page 6.2 : EVS Controller

EVS Controller [F1]Record key [F2]Pointing device [F3]VGA & RMT Sync [F4]PGM/PRV Mode	: Start REC : Tablet : Yes : Enable	P.6.2 + Live
[Menu]Quit [C1r+F_]]	Oft CF93PgUp	[F0]P9Dn

Page 7.3 : Special Control Settings

Special C PGM5:[F1]	ontrol Main	Setting RS422	Secor	nd. R\$422
[Menu]Qui	t [Clr	+F_]Dft	EF93P9UP	[FØ]P9Dn

Page 7.4 : Special Control Settings

Special Control Setting	P.7.4
Controle Type	OSD Display
PGM1:[F1]Parallel	CF5IMain
PGM2:[F2]Parallel	CF6IMain
PGM3:[F3]Parallel	CF7IMain
PGM4:[F4]Parallel	CF8IMain
[Menu]Quit [Clr+F_]Dft	EF91P9UP EF01P9Dn

## Page 7.5 : Special Control Settings

Special Control Setting Controle Type PGM5:[F1]Exclusive	0SD Display
[MenulQuit [Clr+F_]Dft	CF9JPgUp CF0JPgDn

## 1.1.2. New OSD Display items Redundant Hot Swap PSU (Optional)

With redundant power supply units installed, the OSD information **!PSU1** or **!PSU2** is displayed on the OSD when one unit fails (or if one of the power supplies has no power lead connected).

#### OSD Monitoring on the Input Channels (XT[2] only)

Timecode information, the Cam Name defined and the audio monitoring display can now be displayed on the input monitoring display. Alt-R in the shift-F2 screen toggles the OSD on or off on the input monitoring.

Allows the user to disable the PGM/PRV mode from appearing on the remote's main menu ([A] Button).

Multicam is now capable of operating in LSM Base Config with 5 play channels assigned. This added Protocol assignment page is where the user can define the protocols and ports to manage this channel. The LSM remote by itself cannot control 5 PGM channels at one time, two remotes or devices must be used.

This allows channels to either be controlled in 'Exclusive' control (the exclusive controller being set by 2nd Control Mode) or in Parallel Mode.

In Parallel mode, the user can also define which device will manage the OSD display characters.

This page is the same as Page 7.4, but assigns PGM5.

# 1.1.3. VGA Setup Screen Additions Information Window



The Info Window now displays more detailed information about the configuration of the server. On XT[2] servers, it displays in red configuration parameters that are not compatible with XT servers.

#### **VITC/ANC Management**

There is a second page available on the Shift-F2 page on **XT[2] servers**, this page allows channel-by-channel management of VITC or ANC TC management. For more Information refer to section <u>4.1.2 of the Version 8.04 -</u> <u>Software Technical Reference Manual.</u>

In SD, the page displays:

SH+ESC:UGA EXPLORER	(SH)F3:RESET(ALL)	F6:KW1 F7:KW2 F8:SRCH F9:CLIP F10:PLST
Time Code Setting PLAY1	PLAY2 REC1	REC2
TC REF	LTC	LIC
IN LOOP D-UITC Lines	19-21	12221
SD OUT D-UITC Ko Lines UserBits	No	
TAB:SELECT ITEM <-/-	>:CHANGE OPTION F4:SF	AVE AS F5:LOAD

In HD, the page displays:

Time Code	Setting PLAY1	PLAY2	REC1	REC2	
TC REF			LTC	LTC	l
IN LOOP D-UITC Lines			14-16	14-16	
HD OUT HANC LTC UserBits	No	No			
HANC VITC UserBits	In Yes	No			
SD OUT D-VITC Lines UserBits	No				



## XNet[2] Network monitoring screen

H+ESC=UGA_EXPI	ORER (SH)F3:	SDTI NETWORK RESET (ALL)	MONITORING F6:KW1 F7:KW2	F8 : SRCH	F9 = CLIP	Zi: F10:PLST
27 maxs 20200 Srv	29 XFile 10010 Mst	02 LSM2484 24840 Mst/A	03 LSM-XT2 31780(Loc) Mst/A			
					Station	4 4 4
-Z->: CHANGE E	PAGE Palle: SN	Sowe RETURN	RST COUNTER	SPACE:	PAUSE	

A new set of screens has been added in Shift-F4 to enable more accurate monitoring of the SDTI network status.

#### Information displayed

All the machines are displayed in the logical connection order: i.e., the way they are effectively connected on the network.

For each machine, the display shows:

- The net number + name
- The serial number
- The main network configuration setting (server, master, or client).

The background colour of the machine means:

- Blue: effective server
- Grey: not currently server

The colour of the text indicates the video network overload (based on how many SDTI network mailboxes are used):

- White: ok, less than 90% capacity
- Red (over 90%): risk of network overload.

The colour of the link indicates the physical link status between two machines:

- green: OK
- red: errors

Pressing the **Space bar** pauses or restarts the monitoring.

Pressing [Enter] resets the counters.

SH+ESC:UGA EXPLORER	(SH)F3:RESET(A)	LL> F6:KW1	F7:KW2 F8:SRC	F9:CLIP F10:PLST
SDTI Sn PrvSn N	ame CpLk Frm	МЪ		
811L 29010 23650 m Mg1 23650 51980 M	du xt2 0000 0000 NH 1 0000 0000	11		
M28 51980 29010 X	File 0000 0000	11		
Refresh time: 023/0	30 s [+/-] Chang	ge time [F5]	Refresh	Station: 3/3
Varabase check: Ok	Prin: SN Sowt	RETURN: RET SI	OT SPACE: PAL	ISE

Pressing [->] displays a new screen with the information of the list of machines with error counters information. Ideally there should be no errors shown here, but practically until the whole network is configured and connected errors will be logged. Once the whole Network is Setup and running, the counters should be reset by using the return key.



Any errors shown represent a fault with the network, In operating conditions, when all machines are connected, the CpLk (electrical quality of the network) and Frm (checksum on the data packets) counters should not increase at all.

The location of any errors can be determined referring to the serial numbers where the counters are registering errors. Generally replacing a cable used in this location will clear the fault.

#### Server monitoring

The first page of the Server Monitoring section makes it possible to monitor the Disk Status, Genlock and Timecode of the XT server.

It is available by selecting SHIFT-F5 in the Multicam application. For more information refer to section 4.3 of the Version 8.04 - Software Technical Reference Manual.

isk	Status									
aid	Map Raid Ø	~1	Raid	1	~	Raid	2	~1		
H D ·	J/U USK!	UK Ole	UK	01-	UK	OK	290	UK OL		
/D .	Rebuild 26	922	/	UK	OK	UK	1	UK		
enl	ock status			Ĥ	nalog LTC	stat	us			
K	since 19/11/07 - 16	5:01:39	7	1	0:47:59:11	1 <l< td=""><td>OST&gt;</td><td>Drifts</td><td>: 00</td><td>0</td></l<>	OST>	Drifts	: 00	0
ime	Code Status	Rec1	Rec2 R	ec3						
TC	LIC jumps	005	พพร พ	45						
	LIC threshold	050	250 2	50						
	Peak alerts	004	004 0	14						
	Peak Limit (sec)	000	212 2							
	Frequency alerts	000		99						
	Frequency Number	OF O								
GED	IIGER jumps	004	004 0	14						
oEn	USER thusehold									
	OSLN CHIESHOIU	030	000 0	50						

#### Loop Mode



Loop mode is now possible on an XT[2] Server, however it can not be performed internally and requires a physical connection (BNC to BNC cable) between the BNC socket marked LOOP on the back plane and an output from the channel to be replayed (the LOOP connector overrides the connection to input 1 of the XT when the LOOP

function is enabled on the remote panel). The Loop socket may not be present on all XT[2] machines but can be fitted if necessary.

#### Make Local

If a Play-list is created that contains clips from a network server, there is now a command to make the clip local. To select this feature, recall the playlist, press menu and the 'Make Local (B)' key. The network clips in the list will be copied to the local machine in the Page chosen as Playlist receive page in P3.3 of the Setup menu.

#### **Undo and Redo**

This feature is in the secondary menu of the playlist editing function, so that it is not always considered when looking to recover a previous state within a playlist. It allows 9 levels of undo and redo as long as the playlist is not exited. If the playlist is exited the ability to undo or redo is lost. To see if it is possible to undo or redo the last actions, select menu while in playlist mode, the (C) and (D) soft menu keys will display these functions.

In Timeline the Undo and Redo feature is on the primary menu when available.

#### **Merge Playlists**

From the **clip playlist** page on the VGA, it is possible to merge two playlists by copying a playlist (ctrl + c) and then pasting it to an existing playlist (ctrl + v). The copied playlist will be added at the end of the destination playlist when the confirmation message is acknowledged. This merge function now also supports merging network playlists onto local ones.



# 1.2 New hardware features

## 1.2.1. MTPC boards A2/A3 and A2/A4

These boards are in newer XT[2] servers and have additional features such as being able to boot from the USB port, these boards have no floppy disk drives. **Care must be taken when upgrading and particularly downgrading these machines**. Please see the document <u>Multicam 8.04.33 Installation Guide</u> on the EVS website.

## 1.2.2. External Raid Array XT-HDX FOR XT[2] Server



It is now possible to add external storage with up to 15 disks to an XT[2] server. Please see <u>section 3.4.3 in the Hardware Technical</u> <u>Reference manual</u> for more information.

# 1.3 New System features

There are new features for the management of XT servers, please refer to the relevant sections Version 8.04 - <u>Software Technical Reference Manual</u>.

- Online Rebuild of the video disk RAID (XT[2] only) section 2.3.14.1 Disk errors and disconnection
- Overwrite VITC on Output Video section 4.1.2
- Network priorities per channel on the server The selection of pgm channels on the local server to have a higher priority when playing network clips or trains section 4.1.3
- Support for 334M ancillary data packet information section 4.1.4
- Load/ Save of setup parameters to distinguish operational settings from technical settings section 4.1.5 Saving and loading setup files
- Bootable USB installation for MTPC boards A2/A3 and A2/A4 please see the document <u>Multicam</u> <u>8.04.33 Installation Guide</u> on the EVS website.

# 1.4 Bug Fixes up to 08.04.33

Please see the <u>Release Notes</u> in the Download Center of the Website (Support & Training page – Package 8) to determine if a previously reported bug has been fixed.

# 1.5 Known Issues

- Create a playlist and load it. If you go back to live and move to another machine the clip that was last loaded on the player, the playlist will not reload.
- Occasionally the clip TC displayed on the remote in timeline mode may not be accurate.
- Setup Menu, Audio Meters Adjustment : when this parameters is set to 10 or 12dB, the audio meters on the OSD disappear.
- When loading a clip or playlist after a network train, then marking a cue live, the cue is marked on the local trains, not on the previously loaded network train.
- Freeze on OUT point in record trains in target tracking doesn't work when in PLAY VAR **only**. It is OK in normal play.
- When pressing BROWSE in playlist mode, this can cause the AUX clip to start playing. If the user pushes the play key or moves the lever immediately after that, the playlist will start while the AUX clip is already playing, thus they will not be synced properly. To avoid this, before starting the play again, press the PLST key first to recue the playlist, or move the jog dial.
- Sometimes that after upgrading, the "Audio IN/OUT" field (type of audio connectors installed on the system) has been reset to "None". <u>Always check that the value of this field is the same before and after the upgrade</u>. Adjust the value after upgrading if necessary.
- In ADA Adjustment mode, Output 4 actually shows the video incoming on Input 2 rather than Input 4 (bug not present in XT[2]).
- In Load Playlist conditional, when a different playlist is loaded on 2 PGMs, the playlist name displayed on the first PGM corresponds to the name of the playlist loaded on PGM2. The images are correct.
- After having done a search on the remote, the browse function always browses in the results of the clip search, it is not then possible to browse in the clips of the remote.

# 1.6 Limitations

- Timeline should not be used on XT1 risks of audio problems in some configurations.
- OSD on the monitoring of the recorders is only available in Multicam mode and Replay-Only mode.
- Internal loop : in audio embedded, you always get the embedded audio, whether the loop mode is set to video+audio or video only.
- Clear Video Disks from EVS Maintenance Menu is necessary when upgrading from version 04.xx.xx, 5.03.xx or lower ! This is not necessary when upgrading from version 05.04.16 or higher.
- The internal loop mode is not available with HCTS HD systems or with Super Motion systems.
- The keyword file must be distributed to all systems on a network by the Network Server. However, if this
  machine is disconnected for any reason, another server will automatically be designated as Network
  Server and will now be in charge of distributing the keyword file. If the "old" Network Server is
  reconnected to the network but does not recover automatically its Network Server status, the machine
  acting as the current Network Server must be disconnected in order to allow the "old" one to take back
  that job and distribute the keyword file again. This will be resolved in a future version by allowing a
  system not acting as Network Server to distribute keyword files as well.
- When playing HD Super Motion material through the network with the default settings (HD video bitrate 100Mbps and network speed 540Mbps), the network is close to its performance limit and this may cause occasional "freezes". Playback at 50% or 33% dependant on camera type, is OK. If you want to play super motion material on air at 100% speed, you should make a local copy of the clip first, or work with the 1485Mbps network.
- Resetting the "Protect Clip Pages" parameter in the setup does not reset the protect status of existing clips.

# **1.7 Clip Compatibility**

- All clips created with Multicam 5.04.16 or higher are compatible with version 08.04.33. Multicam 9 files have a different structure and will not be compatible with previous versions.
- <u>Important note:</u> if you downgrade from Multicam 08.04.33 to Multicam 08.00.xx or Multicam 08.01.xx, clips will still be present but the system will show that 1 video disk is disconnected → you have to start a disk rebuild (if you need to keep the clips), or clear clips to reconnect this disk.
- Clips created on XT[2] in configurations not available on XT servers will not play correctly on XT servers ! Those configurations are:
  - o SD Mjpeg 625i 608 lines
  - SD Mjpeg 525i 480 lines and 512 lines
  - o SD IMX D10
  - o SD MPEG2 i-field
  - o HD 720p with horizontal resolution of 640 and 1280
  - o HD 1080i with horizontal resolution of 1536 (only incompatible in NTSC), 1600 and 1920.
  - HD AVID DNxHD® Codec
  - o ProRes Codec
  - "CLEAR VIDEO DISKS" from the EVS Maintenance Menu must be done when upgrading from:
    - any version lower than 05.04.16 to version 08.04.33
    - o any version of multicam 9 to a version of 8 or lower!!