



## Service Issue Alert

**Equipment:** LDK6000 Super expander

**Problem :** Loss off lens iris control

**Description of Remedy:** Connector inside super expander becomes unplugged due to tension on umbilical.

**Remedy:** Remove top cover of super expander and secure connection

