

Quick Start Guide OKI - OMNEO Keypanel Interface KP 12 CLD




Reference View - OKI KP 12 CLD

Description

RJ-45 Connectors (2)

1. J1 & J2

2. J3



KP 12 CLD Expansion Box with the OKI Board installed

LC Fiber Connector (Optional)



Cable included with OMNEO Keypanel Module

Included:

- · OMNEO Keypanel Module
- Rear Panel, KP 12 CLD, Expansion
- 2 Screw, 4-40 x .25 LG.
- 3 Screw, PH, 4-40 x 3/16 LG.
- · Safety Instructions ST-CO
- · OKI Quick Start Guide
- OKI Documentation Resource Disk

Requirements:

You must have the following:

- Phillips Screwdriver
- Hex Nut Driver

Firmware Requirements

KP 12 CLD version 1.30


IMPORTANT The keypanel firmware must be updated before you install the OKI module into the keypanel.

OKI Installation – KP 12 CLD

To install the OKI board set for the KP 12 CLD, do the following:

NOTE: Because all the changes are made to the expansion box, remove the expansion box from the KP 12 CLD unit.

- Power off the KP 12 CLD unit.
- 2. Remove the **expansion box** from the KP 12 CLD unit.



NOTE: Steps 3 and 4 are only necessary if an RC option is installed.

- 3. Using a hex nut driver, remove the **12 hex screws** from the KP 12 CLD expansion box.
- Using the same screwdriver, remove the eight (8) pan head screws from the KP12 CLD expansion box.
- 5. Using a Phillips screwdriver, remove the **six (6) flat head screws** from KP 12 CLD expansion box.


F01U280811 Rev 01 01/2013



Quick Start Guide OKI - OMNEO Keypanel Interface KP 12 CLD

- 6. Remove the KP 12 CLD expansion box cover.
- 7. If installed, remove the **RVON standoffs**.
- 8. Replace the standoffs with the provided **pan head** screws (3).

Caution: Ensure that all RJ-45 connectors on the board are flush with the chassis openings.



 Using the provided pan head screws (2), secure the OKI board set to the OKI KP 12 CLD expansion box replacement cover.




Detail A



Detail A

NOTE: It is easier to install the OKI board set to the OKI KP 12 CLD expansion box back panel while the board set and the chassis are laying upside down, see picture below.



NOTE: Align the red stripe on the cable with Pin 1.

- Attach one end of the provided ribbon cable to J2 on the OKI board set.
- 11. Attach the **other end of the ribbon cable to J5** on the KP 12 CLD expansion box main board.
- 12. Replace the existing cover with the OKI KP 12 CLD expansion box cover.

Caution: Ensure that all RJ-45 connectors on the board are flush with the chassis openings.

- 13. Replace the eight (8) pan head screws.
- 14. Replace the six (6) flat head screws.
- 15. Replace the 12 hex screws.

16. Using the existing screws, secure the **OKI KP 12 CLD expansion box cover** to the chassis.



17. Remount the **KP 12 CLD expansion box** to the KP 12 CLD unit.