Sony Corporation

No. HDCM15-042-TN

Technical News

Issued : June 29, 2015 Subject: Software Release [SY-PLD: V3.03]

[Applicable Model]

| Model / Destination | Serial Number | Number of Unit |
|---------------------|---------------|----------------|
| HDC1700 CED | | |
| HDC1700 E33 | | |
| HDC1700 JN4 | | |
| HDC1700 SYL | | |
| HDC2000 CED | | |
| HDC2000 J4 | | |
| HDC2000 JN3 | | |
| HDC2000 SY3 | | |
| HDC2100 J4 | | |
| HDC2400 CED | | |
| HDC2400 E33 | | |
| HDC2400 JN4 | | |
| HDC2400 SYL | | |
| HDC2500 CED | | |
| HDC2500 E33 | | |
| HDC2500 JN4 | | |
| HDC2500 SYL | | |
| HDC2550 CED | | |
| HDC2550 UC7 | | |
| HDC2570 CED | | |
| HDC2570 UC7 | | |
| HDC2580 CNB | | |
| HDC2600 J4 | | |
| HDC4300 CED | | |
| HDC4300 CNB | | |
| HDC4300 J4 | | |
| HDC4300 JN4 | | |
| HDC4300 SYL | | |

[Description]

The software files of SY-PLD V3.03 are released to improve the applicable models. Upgrade it as necessary.

[Change Point]

- 1. Improve the jitter of SDI_MONI_OUT Improve the timing jitter of SDI_MONI_OUT.
- Correct the ECS error of HDC2500.
 There might be rarely a case where the color balance of the output image is shifted only one frame when the ECS is changed in series. This error is corrected.

[Preparation]

<Software Files>

File name:

hdc2000_sy.pkg

 PLD data for SY-408 on HDC2400 / HDC2500 / HDC2550 / HDC2570 / HDC2580 / HDC2600 / HDC2000 / HDC2100 / HDC1700

hdc4300_sy.pkg - PLD data for SY-408 on HDC4300

* Please contact to your local Sony's service office for obtaining the software files.

<Others>

USB memory 1 piece

[Installation Procedure]

Refer to the description in the MAINTENANCE MANUAL.

[Confirmation / Adjustment]

Confirm if the SY-PLD version is V3.03 from the camera menu DIAGNOSIS – <ROM VERSION> page.

No adjustment is required.