



Broadcast Products Technical Bulletin 20-2007-017

DATE: January 15, 2007

SUBJECT: NO POWER UP WITH HDVF-7700

MODEL: HDC1000/LB
 HDC1000/LW
 HDC1000/LW1
 HDC1000/LW2
HDLA1500/B
 HDLA1500/B
HDLA1500/B1
HDLA1500/B2
 HDLA1500/B2
HDLA1500/W
 HDLA1500/W
HDLA1500/W1
 HDLA1500/W1
HDLA1500/W2
 HDLA1500/W2
HDLA1505/W
 HDLA1505/W

DESCRIPTION

The VF may not power up when HDVF-7700 is attached. The VF also may not power up with HDVF-9900 due to hot-swap.

PARTS REQUIRED

Part No.	Description	Qty.
1-468-861-12	Switching Regulator	1

ORDERING INFORMATION

To order parts online, go to: <http://www.sony.com/servicesplus>. For service and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

SERIAL NO:

HDC1000/LB	12,026–12,036
HDC1000/LW	10,001–10,015
HDC1000/LW1	11,001–11,020
HDC1000/LW2	12,001–12,025
<i>HDLA1500/B</i>	<i>40,006–40,010</i>
HDLA1500/B	10,036–10,040
<i>HDLA1500/B1</i>	<i>41,019–41,028</i>
<i>HDLA1500/B2</i>	<i>42,042–42,043</i>
	<i>42,059–42,068</i>
HDLA1500/B2	12,011–12,020
	12,034–12,041
<i>HDLA1500/W</i>	<i>40,001–40,005</i>
	<i>40,011–40,020</i>
HDLA1500/W	10,001–10,035
<i>HDLA1500/W1</i>	<i>41,001–41,018</i>

(Part 1 of 2)

Italicized information in green applies to customers outside the United States.

HDVM06-059R

MODIFICATION PROCEDURE

Replace the switching regulator with a new one.

NOTE: For replacement details, refer to the maintenance manual. Be sure to remove the red pin attached to the power supply.

CONFIRMATION

Confirm that the camera and VF operate properly.

SERIAL NO: (Continued)

HDLA1500/W1 11,001–11,039

*HDLA1500/W2 42,001–42,041
42,044–42,058*

HDLA1500/W2 12,001–12,010

12,021–12,033

12,042–12,061

HDLA1505/W 40,001–40,031

HDLA1505/W 10,001–10,002

(Part 2 of 2)

Italicized information in green applies to customers outside the United States.