



Broadcast Products Technical Bulletin 20-2010-063

DATE: May 31, 2010

SUBJECT: VIDEO DISTURBANCE

MODEL: HDC1000/LB
HDC1000/LW
HDC1000/LW2
HDC1500/L
HDC1500/L2
HDC1550/F
HDC1550/K1

DESCRIPTION

Output video may lose synchronization and become disturbed on occasion. Output video returns to normal after several frames because data refreshes every vertical cycle.

To correct the symptom, upgrade the TG PLD.

ORDERING INFORMATION

SERIAL NO:

HDC1000/LB	10,001–12,036
<i>HDC1000/LW</i>	<i>40,001–40,005</i>
HDC1000/LW2	10,001–12,036
<i>HDC1500/L</i>	<i>40,001–40,115</i>
HDC1500/L2	10,001–12,235
<i>HDC1550/F</i>	<i>40,001–40,045</i>
HDC1550/K1	10,001–10,036

Contact your Sony regional service center to arrange for upgrade of the PLD, which requires specialized skills and equipment. The following document lists all contact telephone numbers:

Technical Bulletin 00-1999-000

Italicized information in green applies to customers outside the United States.

HDVM08-136