



## Broadcast Products Technical Bulletin 20-2010-066

DATE: May 31, 2010

SUBJECT: **WHITE NOISE ON LOWER LEFT WHEN  
CONNECTED TO HDCU-900/950**

MODEL: *HDC1000//ULW*  
*HDC1000/LB*  
*HDC1000/LW*  
*HDC1000/LW*  
*HDC1000/LW1*  
*HDC1000/LW2*  
*HDC1000R/LB*  
*HDC1000R/LW*  
*HDC1000R/LW*  
*HDC1400//UL*  
*HDC1400/L*  
*HDC1400R//UL*  
*HDC1400R/L*  
*HDC1400R/T*  
*HDC1450//UF*  
*HDC1450/K*  
*HDC1450R//UF*  
*HDC1450R/K*  
*HDC1500//UL*  
*HDC1500/L*  
*HDC1500/L*  
*HDC1500/L1*  
*HDC1500/L2*  
*HDC1500/T2*  
*HDC1500R//UL*  
*HDC1500R/L*  
*HDC1500R/T*  
*HDC1500R/T*  
*HDC1550//UF*  
*HDC1550//UF1*  
*HDC1550/F*  
*HDC1550/K1*  
*HDC1550/K2*  
*HDC1550R//UF*  
*HDC1550R/K*  
*HDC1580/L*  
*HDC1580/L1*  
*HDC1580/T*  
*HDC1580R/L*  
*HDC1580R/T*

SERIAL NO: **ALL**

*Italicized information in green applies to  
customers outside the United States.*

### DESCRIPTION

When the camera is connected to HDCU-900/950 and operated from the control panel, white noise several pixels in width may appear on the left of a specific line approximately one-third from the bottom of the picture.

To correct the symptom, upgrade SDI-84-PLD to V1.14/V2.02.

### ORDERING INFORMATION

Contact your Sony regional service center to arrange for upgrade of this software, which requires specialized skills and equipment. The following document lists all contact telephone numbers:

Technical Bulletin 00-1999-000

HDCM10-004