Release Notes

Release 5.0.2.0

Version: 1.0

Date: 22.07.2014

This document applies to the products

- mc²56 & mc²56MKII
- mc²66MKII
- mc²90
- Nova73 HD & Nova73 compact

It outlines the functions and improvements of Release Version 5.0.2.0.

Please make sure to read the System Update Documentation carefully!

New Functions

Additional features included in version 5.0.2.0:

1) New DALLIS Master Card

Release 5.0.2 introduces a new DALLIS Master card. The new card is called 947/22 and is a combined MADI and RAVENNA card. It can be used as MADI **or** RAVENNA Master card. The card offers the choice of an optical and an electrical port via RAVENNA. The MADI port offers one port that can be used in Singlemode or Multimode by using dedicated SFPs.

With Release 5.0.2.0, the new card replaces the existing MADI Master cards 947/05 and 947/15 and will be used in all new projects with immediate effect.

Please note, that the RAVENNA connectivity of this card is not part of Release 5.0.2.0, but will be given in the future with a software update.

Extensions and fixes

13159 – Push-Event of Monitoring-rotaries has wrong internal number
13142 – CF Card Creator creates CF cards for 990/19 (ext. Bayserver) that don´t work
13134 – DSP Presets Dialog "Delete File" is hidden when trying to delete a folder
13098 – RAVENNA Link connection: All Master and I/O cards flash out of Sync
13075 – External Bayserver without Baycontrol board boot as BAY 0
13011 – n -1 assignments cannot be done via Signal Settings Page anymore

Contacting the Service Department

If you need assistance with updating your system, please contact our service department. The staff will coordinate all necessary steps with you.

Important information which the service department will require is as follows:

- Name and phone number of the contact person
- Time when this person is available
- Number and type of the system(s)
- Current software version
- System configuration data

Telephone support can be given during office hours (Mon – Fri 9:00 – 17:00 hrs CET)

Phone: +49-7222-1002-4000

email: service@lawo.de

Copyright