


REPLACEMENT OF DRIED CAPACITORS ON TSI1000 MOTHERBOARD



Note: Stripe on Capacitor marks negative side.
Positive side is marked on motherboard at each capacitor position.