

[Internal Use Only] <<The information in this document should not be used for other purpose than Sony and/or Sony authorized dealers (ASC/ASD).>>

Sony Corporation

No. HDCM13-050R-TN

Technical News

Issued : August 29, 2013

Revised : September 9, 2013

Subject: Software Release (V1.42 => V1.43)

[Applicable Model]

Model / Destination	Serial Number	Number of Unit
HDC2000 CED		
HDC2000 J4		
HDC2000 JN3		
HDC2100 J4		
HDC2400 CED		
HDC2400 E33		
HDC2400 JN4		
HDC2400 SYL		
HDC2500 CED		
HDC2500 E33		
HDC2500 JN4		
HDC2500 SYL		
HDC2550 CED		
HDC2550 UC7		
HDC2580 CNB		
HDC2600 J4		

(Rev.1) HDC2570 is deleted from the applicable models.

[Description]

Update software for HDC2500 series (V1.43) is released. Upgrade it as necessary.

[Change Point]

1. Correct the setting of INCOM1
Correct the error that the side tone is not output from RIGHT side.
2. Correct the VF Detail setting in 720P mode
Correct the VF Detail effective area in 720Pmode.
3. Improve the communication with the serial lens
Improve that the iris indication may not be updated on rare occasion.

[Preparation]

<Software File>

File name:

hdc2000_app.pkg - Software file

* Please contact to your local Sony's service office for obtaining the software file.

<Others>

USB memory 1 piece

[Installation Procedure]

Refer to the MAINTENANCE MANUAL.

[Confirmation]

Confirm the CAMERA APP version by the camera menu DIAGNOSIS – <ROMVERSION>(D3) page.

CAMERA APP V1.43