

Sony Corporation

No. HDVM06-181-TN

Technical News

 Issued : March 12, 2007

Subject: Software PLD Version Upgrade V1.12

Applicable Model(s) (Destination)	Serial Number(s)		Number of Unit(s)
HDCU1000//ULCED	400001	- 400104	104
HDCU1000/L CED	40001	- 40013	13
HDCU1000/L UC5	10001	- 10060	60
HDCU1000/L1 CED	41001	- 41085	85
HDCU1000/L1 J2	32031	- 32036	6
HDCU1000/L1 UC5	11001	- 11112	112
HDCU1000/L2 CED	42001	- 42125	125
HDCU1000/L2 UC5	12001	- 12453	453
HDCU1000/T J2	30001	- 30035	35
HDCU1000/T1 J2	31001	- 31020	20
HDCU1000/T2 J2	32001	- 32030	30
HDCU1000/T2 J2	32037	- 32056	20
HDCU1000/T2 J2	33001	- 33020	20
HDCU1080/L CNB	50001	- 50075	75
HDCU1500//ULCED	400001	- 400184	184
HDCU1500/L SYL	10001	- 10025	25
HDCU1500/L1 SYL	11001	- 11089	89
HDCU1500/L2 SYL	12001	- 12309	309
HDCU1500/L2 SYL	13001	- 13010	10
HDCU1500/T J4	30001	- 30015	15
HDCU1500/T1 J4	31001	- 31060	60
HDCU1500/T2 J4	32001	- 32140	140
HDCU1500/T2 J4	33001	- 33020	20
HKCU1005 SYM			
HKCU1005/1 SYM			
HKCU1005/2 SYM			

This Technical News includes information on Software Version Upgrade. Please contact to your local Sony's sales/service office for the details.