



Camera

Date: **November 16, 1998**Model: **DXF-51**Serial No: **30,001–31,790**Subject: **DXF-51 AND DXC-637 DO NOT POWER
UP****DESCRIPTION**

When DXF-51 units are connected to a DXC-637 which is connected to a CCU-M7 with a 300m cable, DXF-51 and DXC-637 units may not power up.

To reduce voltage drop at power up, perform the following modification procedure.

PARTS REQUIRED

Part No.	Description	Qty.
1-216-679-11	Res, Chip, 15kΩ, R501, R505	2

MODIFICATION PROCEDURE

Change the following components on G board, side B:

Ref. Number	Zone	New Part
R501	F-5	15kΩ chip resistor
R505	E-3	

CONFIRMATION

No adjustment is required.

Power on and ensure picture is correctly displayed.