



Camera

## Video Products Technical Bulletin 30-2009-055

DATE: **April 6, 2009**SUBJECT: **POWER SHUTS DOWN IN HIGH-TEMPERATURE ENVIRONMENTS**MODEL: **DXF-51//K4**

SERIAL NO:

DXF-51//K4 119,002–119,471

**DESCRIPTION**

Power may shut down or the unit may not start when used for long periods of time in high-temperature environments.

**PARTS REQUIRED**

Part No.	Description	Qty.
1-218-881-11	Res, Chip, 1608, 27 k $\Omega$	1

**ORDERING INFORMATION**

To order parts online, go to: <http://www.sony.com/servicesplus>.  
For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

**MODIFICATION PROCEDURE****VF-81B Board (Side B, Zone A-1)**

Replace R266 (47 k $\Omega$ ) with a new 27 k $\Omega$  resistor.

DXCM08-005