



## Broadcast Products Technical Bulletin 20-2007-148

DATE: **August 13, 2007**SUBJECT: **PARTS REGISTRATION—SUB (LENS) HARNESS  
IN FRONT BLOCK**MODEL: **HDC1000  
HDC1100  
HDLA1500  
HDLA1503  
HDLA1505**SERIAL NO: **ALL****DESCRIPTION**

The sub (lens) harness located in the front block is available as a service part. (See Figure 1.)


Model	Part No.
HDC1000, HDC1100	1-963-954-11
HDLA1500 series	1-963-931-11

**ORDERING INFORMATION**

To order parts online, go to: <http://www.sony.com/servicesplus>.  
For service and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

HDC1000, HDC1100



HDLA1500 SERIES




Figure 1