

Camera



WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

Broadcast Products Technical Bulletin 20-2009-091

DATE: May 4, 2009

SUBJECT: PARTS REGISTRATION—OUTSIDE PANEL SUB ASSEMBLY


MODEL: HDC1400//UL HDC1400/L HDC1400/T HDC1400/T HDC1450//UF HDC1450/K HDC1500//UL HDC1500/L HDC1500/L HDC1500/L1 HDC1500/L2 HDC1500/T HDC1500/T2 HDC1550//UF HDC1550//UF1 HDC1550/F HDC1550/K HDC1550/K1 HDC1550/K2 HDC1580/L HDC1580/L1 HDC1580/T HDC3300/L HDC3300/L HDC3300/T HDC3300/T

SERIAL NO: ALL

Italicized information in green applies to customers outside the United States.

DESCRIPTION

The outside panel sub assembly is available as service part number **A-1128-448-A**. (See Figure 1.)





ORDERING INFORMATION

To order parts online, go to: <u>http://www.sony.com/servicesplus</u>. For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

HDVM08-175

Broadcast Professional Products Asia • Sony Australia • Broadcast Professional Products Europe • Sony Canada Ltd. • Sony Electronics Inc. USA • Sony Broadcast and Professional Latin America