



Broadcast Products Technical Bulletin 20-2009-127

DATE: July 20, 2009

SUBJECT: OHB-TYPE SETTINGS REQUIRED WHEN
REPLACING CCD BLOCK

MODEL: HDC1000/LB
HDC1000/LW
 HDC1000/LW
 HDC1000/LW1
 HDC1000/LW2
 HDC1000LBM
HDC1400//UL
 HDC1400/L
HDC1450//UF
 HDC1450/K
HDC1500/L
 HDC1500/L
 HDC1500/L1
 HDC1500/L2
 HDC1500/LA
 HDC1500/LAT
 HDC1500/S
 HDC1500C2
 HDC1500L/T
 HDC1500L2M
 HDC1500LBS
 HDC1500LG
 HDC1500LT
HDC1550//UF
HDC1550//UF1
HDC1550/F
 HDC1550/K
 HDC1550/K1
 HDC1550/K2

DESCRIPTION

When using CCD block with service part number A-1153-996-C:

1. Set SERVICE menu > Page S19 > OHB-TYPE as shown in Table 1.
2. Power the camera ON/OFF twice.

Table 1. OHB-TYPE

Model	Region	OHB-TYPE
HDC1000	All	MULT
HDC1500		
HDC1550		
HDC1400	US and Canada	UC
HDC1450		
HDC1400	Continental Europe	CE
HDC1450		

SERIAL NO: ALL

Italicized information in green applies to customers outside the United States.

HDVM08-030