



## Broadcast Products Technical Bulletin 20-2010-067

DATE: May 31, 2010

SUBJECT: **SUPPORT FOR 3G FIBER TRANSMISSION UNIT  
(HKC-HB10 AND HKC-HB15)**

MODEL: **HDC1000  
HDC1000R  
HDC1100R  
HDC1400R  
HDC1500  
HDC1500R  
HDC1600R**

SERIAL NO: **ALL**

### DESCRIPTION

When installing the 3G FIBER TRANSMISSION unit (HKC-HB10, HKC-HB15), upgrade firmware and PLD to the versions in Table 1.

Table 1

Model	Description	Version
HDC1000 HDC1500 HDC1000R HDC1100R HDC1400R HDC1500R HDC1600R	Firmware	3.00
HDC1000R HDC1100R HDC1400R HDC1500R HDC1600R	PLD DAP-33A	4.00
	PLD DPR-265A	3.00

---

**NOTE:** The 3G FIBER TRANSMISSION unit does not operate correctly with earlier firmware versions.

---

### ORDERING INFORMATION

Contact your Sony regional service center to arrange for installation of this firmware, which requires specialized skills and equipment. The following document lists all contact telephone numbers:

Technical Bulletin 00-1999-000

---

HDCM10-013