



## Video Products Technical Bulletin 30-2009-057

DATE: April 27, 2009

SUBJECT: PARTS REGISTRATION—BNC BRACKET

MODEL: CA-590//U  
*CA-590P//U*  
CA-TX50//U  
*CA-TX50P//U*  
DSR-450WSL  
DSR-450WSPL  
*DSR-650WSPL*  
F23  
F35  
*HDC1000//ULW*  
HDC1000/LB  
HDC1000/LW  
*HDC1400//UL*  
HDC1400/L  
*HDC1400/T*  
HDC1400/T  
*HDC1450//UF*  
HDC1450/K  
*HDC1500//UL*  
HDC1500/L  
*HDC1500/T*  
*HDC1550//UF*  
HDC1550/K  
*HDC1580/L*  
*HDC1580/T*  
*HDC3300/L*  
HDC3300/L  
*HDC3300/T*

SERIAL NO: ALL

*Italicized information in green applies to  
customers outside the United States.*

### DESCRIPTION

The BNC bracket is available as service part number **3-863-319-01**. (See Figure 1.)




Figure 1

### ORDERING INFORMATION

To order parts online, go to: <http://www.sony.com/servicesplus>.  
For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

BIM09-004, BVPM09-002, DXCM09-002  
HDVM09-012