



Broadcast Products Technical Bulletin 20-2011-069

DATE: **June 27, 2011**SUBJECT: **SOFTWARE UPGRADE—VERSION 1.12**MODEL: **HDC-P1//U**

SERIAL NO:

HDC-P1//U 100,001–100,374

DESCRIPTION

Software version 1.12 is available. This upgrade contains the following software versions:

AT ROM V1.12

DPR2 PLD V1.03

ORDERING INFORMATION

Contact your Sony regional service center to arrange for upgrade of this software, which requires specialized skills and equipment. The following document lists all contact telephone numbers:

Technical Bulletin 00-1999-000

PROGRAM IMPROVEMENTS

- When horizontal video is inverted, HD-SDI output is no longer delayed by two lines compared to the external reference.
- In 1080/50i mode, VBS OUT video no longer shifts vertically when started up.
- The CHROMA FILTERS item no longer disappears from the Service menu.

HDCM10-056