



File Edit Device Extras 2



Extender Update via Mini-USB flash drive

Steps

1. Select Extender
2. Identify Extender Type
3. Update Extender
4. Firmware Check

Select Extender

1. Power up the extender and connect it to your computer via mini-USB connector.
2. Then press the **Search Extender** key.
3. Select the detected extender.

Search Extender

#	Drive	Name	Description
01	F:\	40164784 (F:)	Removable Disk

< Back Next > Finish Cancel



Steps

1. Select Extender
2. **Identify Extender Type**
3. Update Extender
4. Firmware Check

Identify Extender Type

1. Automatic extender detection in progress. If the extender is not recognized by the automatic detection, execute the manual extender type detection

Manual Extender Type Identification

Status Log

2019-03-06T13:28:47.849	EXTIMSD.PFW
2019-03-06T13:28:47.849	EXTICPU.PFW
2019-03-06T13:28:47.849	HIDCPU.PFW
2019-03-06T13:28:47.849	CONVGPU.PFW
2019-03-06T13:28:47.849	Extender identification successful

< Back

Next >

Finish

Cancel

**Steps**

1. Select Extender
2. Identify Extender Type
3. **Update Extender**
4. Firmware Check

Update Extender

1. Select the firmware file (*.efw). Modules requiring any update will be automatically highlighted.
2. Start the update.

Firmware File (*.efw)

?5_V0306_IHSEUSA\20180925_V0306_IHSEUSA\20180815_Extender_FW_classic.efw

Browse...

#	Name	Type	Cur. Version	Upd. Version	Cur. Date	Upd. Date	Selected
01	EXTICPU	EXT	B01.35.170515	F01.48.180418	2017-05-15	2018-04-18	☒
02	HIDCPU	HID	B04.01.170213	F04.01.180219	2017-02-13	2018-02-19	☒
03	EXTIMSD	MSD	B01.26.170503	B01.28.180606	2017-05-03	2018-06-06	☒
04	CONVGPU	GPU	B01.46.170509	F01.47.171013	2017-05-09	2017-10-13	☒

Update Progress

0%

Update

2019-03-06T13:30:22.194

Firmware files loaded

< Back

Next >

Finish

Cancel

**Steps**

1. Select Extender
2. Identify Extender Type
3. **Update Extender**
4. Firmware Check

Update Extender

1. Select the firmware file (*.efw). Modules requiring any update will be automatically highlighted.
2. Start the update.

Firmware File (*.efw)

25_V0306_IHSEUSA\20180925_V0306_IHSEUSA\20180815_Extender_FW_classic.efw

Browse...

#	Name	Type	Cur. Version	Upd. Version	Cur. Date	Upd. Date	Selected
01	EXTICPU	EXT	B01.35.170515	F01.48.180418	2017-05-15	2018-04-18	☒
02	HIDCPU	HID	B04.01.170213	F04.01.180219	2017-02-13	2018-02-19	☒
03	EXTIMSD	MSD	B01.26.170503	B01.28.180606	2017-05-03	2018-06-06	☒
04	CONVGPU	GPU	B01.46.170509	F01.47.171013	2017-05-09	2017-10-13	☒

Update Progress



7%

Update

2019-03-06T13:32:31.846 Update of EXTIMSD completed
2019-03-06T13:32:31.846 Extender is restarting

< Back

Next >

Finish

Cancel



Extender Update via Mini-USB flash drive



Steps

1. Select Extender
2. Identify Extender Type
3. **Update Extender**
4. Firmware Check

Update Extender

1. Select the firmware file (*.efw). Modules requiring any update will be automatically highlighted.
2. Start the update.

Firmware File (*.efw)

?5_V0306_IHSEUSA\20180925_V0306_IHSEUSA\20180815_Extender_FW_classic.efw

Browse...

#	Name	Type	Cur. Version	Upd. Version	Cur. Date	Upd. Date	Selected
01	EXTICPU	EXT	B01.35.170515	F01.48.180418	2017-05-15	2018-04-18	☒
02	HIDCPU	HID	B04.01.170213	F04.01.180219	2017-02-13	2018-02-19	☒
03	EXTIMSD	MSD	B01.26.170503	B01.28.180606	2017-05-03	2018-06-06	☒
04	CONVGPU	GPU	B01.46.170509	F01.47.171013	2017-05-09	2017-10-13	☒

Update Progress

100%

Update

2019-03-06T13:32:31.846 Update of EXTIMSD completed
2019-03-06T13:32:44.236 Extender restarted
2019-03-06T13:33:38.555 Update of CONVGPU completed
2019-03-06T13:34:34.700 Update of EXTICPU completed
2019-03-06T13:34:52.390 Update of HIDCPU completed
2019-03-06T13:35:22.638 Finished update process
2019-03-06T13:35:22.638 Firmware update completed. Press next to verify the update.



< Back

Next >

Finish

Cancel

Steps

1. Select Extender
2. Identify Extender Type
3. Update Extender
4. **Firmware Check**

Firmware Check

1. Extender has to be manually power cycled by user. Extender verification will automatically start.

Status Log

2019-03-06T13:36:28.165	Extender is switched off. Please reconnect power supply
2019-03-06T13:36:30.434	Restart successful
2019-03-06T13:36:30.481	Start firmware verification
2019-03-06T13:36:35.161	EXTICPU update successful
2019-03-06T13:36:35.161	HIDCPU update successful
2019-03-06T13:36:35.161	EXTIMSD update successful
2019-03-06T13:36:35.161	CONVGPU update successful
2019-03-06T13:36:35.161	Firmware verification completed