



ALIF100T v4.09.4

Release note

Adder Technology Limited

By: John Halksworth
Date 5th January 2021

Revision History: 1.0

Registered Address:
Adder Technology Limited
Saxon Way,
Bar Hill, Cambridge
CB3 8SL, UK

Adder Corporation
24 Henry Graf Road
Newburyport,
MA 01950
USA

Adder Technology
(Asia Pacific) Pte. Ltd.,
8 Burn Road
#04-10 Trivex,
Singapore 369977

Table of Contents

ALIF100T v4.09.4 release note	1
Scope.....	1
Parts affected	1
Previous version.....	1
Fixed issues since previous release.....	1
Known issues	1
Upgrade instructions	1

ALIF100T v4.09.4 release note

Scope

ALIF100T-DVI, VGA and DP are zero U transmitters in the AdderLink Infinity range.

Parts affected

ALIF100T-DVI
ALIF100T-DP
ALIF100T-VGA

Previous version

The previous live version was v4.07.07

The release package contains the following;

1. Release notes
2. Firmware V4.09.4

Generic	Part No	Associated files
Adder ALIF100T	ALIF100T-DP ALIF100T-DVI	ALIF100T_V4.09.40000 upgrade_dvix2_backup_adder.bin.txd.4.09.40000 upgrade_dvix2_main_adder.bin.txd.4.09.40000
Adder ALIF100T	ALIF100T-VGA	ALIF100T_V4.09.40000 upgrade_dvix2_backup_adder.bin.txf.4.09.40000 upgrade_dvix2_main_adder.bin.txf.4.09.40000

Fixed issues since previous release

20556	Endpoints Host Name contains illegal characters
20561	USB intermittently lost when rebooting a Chyron Graffiti host
20653	Cannot access BIOS on HP PC after reboot
20496	Port stream deck support
20713	Fixed EDIDs to advertise a sRGB color space
Brian-240	Add fixed EDID of 1720 x1440 @30Hz
Brian-49	Thumbnail image collection on Video config page added

Known issues

Currently there are no know issues.

Upgrade instructions

For further support information go to <http://support.adder.com>