



XNetMonitor | VERSION 1.6.12

RELEASE NOTE

> October 2023

Author | CHARES, Robert
Email | r.chares@evs.com

CONTENT

Legal Notice.....	2
New Features.....	4
Bug Fixes.....	6
Known Issues & Limitations	7
Issues.....	7
Compatibility.....	7
Software.....	7



LEGAL NOTICE

Please note that the present product is supplied by EVS Broadcast Equipment SA or any other relevant entity of the EVS Group ("EVS") and is subject to EVS Software License Agreement (available on https://evs.com/sites/default/files/2021-04/Software_License_Agreement.pdf or upon request) along with any applicable additional terms or policies.

By installing, copying, or otherwise using the present product, you agree to be bound by the above-mentioned terms.

DISCLAIMER

This release note and the information contained herein are the sole property of EVS Broadcast Equipment SA and/or its affiliates (EVS) and are provided "as is" without any expressed or implied warranties, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. In particular, EVS makes no warranty regarding the use or the consequences of use of this release note and the information contained herein. Furthermore, EVS may not be held liable for any direct or indirect, incidental, punitive or consequential loss, damage, cost or expense of any kind whatsoever and howsoever resulting from the normal or abnormal use of this release note and the information contained herein, even if advised of the possibility of such loss, damage, cost or expense.

While every effort has been made to ensure that the information contained in this release note is accurate, up-to-date and reliable, EVS cannot be held liable for inaccuracies or errors that may appear in this publication. The information in this release note is furnished for informational purpose and use only and subject to change without notice.

This release note cancels and replaces any previous versions thereof.

COPYRIGHT

Copyright © 2003-2021 EVS Broadcast Equipment SA. All rights reserved.

This release note may not be reproduced, transcribed, stored (in a database or a retrieval system), translated into any language, computer language, transmitted in any form or by any means – electronically, mechanically, printed, photocopied, optically, manually or otherwise – in whole or in part without the prior written consent of EVS.

TRADEMARKS

All product and brand names are registered trademarks and trademarks of EVS or of their respective owners.

IMPROVEMENT REQUESTS

Your comments will help us improve the quality of the documentation. Please send improvement requests, report any error or inaccuracy on this release note by e-mail to doc@evs.com.



REGIONAL CONTACTS

You will find the full list of addresses and phone numbers on the following webpage: <http://www.evs.com/contact>.

RELEASE NOTES ON EVS WEBSITE

The latest version of the release note, if any, and other release notes on EVS products can be found on the EVS download center, on the following webpage: <https://www.evs.com/en/download-area>.

NEW FEATURES

IN 1.6.12

- > Support of Multicam 20.6
- > QR code link to viaportal.evs.com
- > HDR information in server overview

IN 1.6.10

- > Support of Multicam 20.5
- > Support multi-select and select-all when deleting Multicam versions
- > Support SNMP refresh by server group

IN 1.6.9

- > Support of Multicam 20.4

IN 1.6.8

- > Support of Multicam 20.3
- > Display of second PC-LAN IP address
- > Support Live IP QSFP interface monitoring
- > Support RAID configuration 10+2

IN 1.6.6

- > Support of Multicam 20.2
- > Live IP SFP Monitoring

IN 1.6.5

- > Support of Multicam 16.6 and 20.1
- > Display of PTP information
- > Display presence of XHub-VIA IP Aggregator

IN 1.6.4

- > Support of Multicam 16.5 and 20.0
- > Display IP input stream status monitoring

IN 1.6.3

- > Support of Multicam 16.4
- > Support of XT-GO
- > Support of XNet-GO

IN 1.6.2

- > Support of Multicam 16.3
- > Support of PTP Genlock
- > Support of trap in case of division by 0 error
- > Support of trap in case of R4X issues
- > Support of trap in case of system backup issue
- > Support of trap in case of temperature issue

IN 1.6.1

- > Support of Multicam 16.2
- > Display of output resolution for 1080p-to-UHD-4K upscale
- > Support of XNet speed XNet-Via
- > Display XNet-Via interface parameters
- > Display of XT IO board

IN 1.6.0

- > Support of Multicam 16.1
- > Support of XS-Via
- > Support of server temperature measurements
- > Support of HW Edition
- > Support of HDR
- > Support of interface parameter

IN 1.5.5

- > Support of Multicam 16.0
- > Support of XT-Via
- > Support of 10+1 RAID configuration

IN 1.5.2

- > Support of Multicam 15.1
- > Support of Windows 10
- > Signed installers and application
- > Support of XS4K
- > Support of SLSM 16x

BUG FIXES

IN 1.6.11

- > The server log extraction could occasionally fail due to No Response to SNMP Polling error

IN 1.6.10

- > On XT-GO, the LSM-GO Remote was wrongly displayed in the controller section
- > The version build number was not correctly displayed in the About window
- > Hitting some keyboard keys could result in disconnecting from the VGA console
- > Disconnected XT server disks could wrongly appear as connected in the Storage section

IN 1.6.9

- > Refreshing SNMP Information could fail for XT servers running on Multicam 15.3 or earlier

IN 1.6.6

- > When retrieving the server status, one could obtain an unexpected error value
- > Sometimes Multicam installations could be displayed as failed despite correct installation
- > The number of available XT license codes was limited to 50

IN 1.6.5

- > On XT-GO, the Spotlight base config was wrongly indicated as Multicam LSM

IN 1.6.4

The status of disconnected disks was sometimes not correct

IN 1.6.3

- > The location of the disconnected disk on the external storage array was not correct
- > The h.264 proxy was not displayed correctly in the Audio-Video settings
- > The temperature unit could not be changed to Fahrenheit

IN 1.6.2

- > The TriLevel Genlock signal was not correctly displayed in the interface
- > When working in ST 2110 the channel section displayed a missing embedded audio error
- > The XNet server and visibility were not correctly displayed in the multiple servers view
- > The position of faulty disks were not correctly indicated in the storage section

IN 1.6.1

- > The disk capacities on XT-VIA/XS-VIA were not properly displayed graphically

IN 1.5.2

- > Errors with Nearline Servers hosting large drives

KNOWN ISSUES & LIMITATIONS

ISSUES

SINCE 1.5.2

- > Remote desktop window resize may lead to incorrect display

BEFORE 1.3

- > When a recorder turns red due to a signal problem, the recorders below turn red also
- > When a version anterior to Multicam 11 is running with a zero rec configuration, the value of the remaining capacity parameter is not correct
- > When a server produces many errors, log files can grow rapidly (11551)
- > XNet Monitor does not list a remote in hypermotion mode (12329)
On IPDP Spotbox, when the IPDP connection fails over to another port via the redundancy mechanism, the information is not displayed on the XNet Monitor..

COMPATIBILITY

SOFTWARE

- > XNetMonitor is compatible with version 12.02 or later of Multicam
- > XNetMonitor requires .Net 4.6.1 on Windows 7, 10, Server 2008
- > Windows XP and Server 2003 are no longer supported



EVS Broadcast Equipment SA

RUE DU BOIS SAINT JEAN 13, B-4102 SERAING, BELGIUM

Copyright © 2003-2021 EVS Broadcast Equipment SA. All rights reserved.

This release note may not be reproduced, transcribed, stored (in a database or an retrieval system), translated into any language, computer language, transmitted in any form or by any means – electronically, mechanically, printed, photocopied, optically, manually or otherwise – in whole or in part without the prior written consent of EVS.

All product and brand names are registered trademarks and trademarks of EVS or of their respective owners.

EVS.COM