

Dear Customer!

With this Overview you receive the latest Software information about your Grass Valley Imaging Products you work with every day. Please be aware that Software and Firmware are the heart of all devices.

Therefore we **STRONGLY** recommend:

Software updates should only be done AFTER having checked your complete environment and third-party-applications for compatibility.
Please read all Release-Notes carefully before taking any action.

Errors that occur due to wrong upload-procedures or wrong software can sensitively damage your equipment; so if you do not feel comfortable or in case you prefer to have the update done by our field service on site, please get in touch with your local Grass Valley Service engineer who will be ready to assist you. All contacts to Grass Valley you find [<< here >>](#)

A c t u a l

D i s c o n t i n u e d

O u t o f S e r v i c e

Actual = Product in Production and Service

Discontinued = Product out of Production but in Long Term Product Service (LTPS)

Out of Service = Product out of Service, we can try to help you
But this is just on best effort basis without any warranty!
Software will not longer be improved in "Out of Service" – Status!

Content

Page 02 = Actual Products
Page 03 + 04 = Discontinued Camera Products in LTPS
Page 6 = « Package » Concept

Page 05 = Discontinued Camera Products – Out of Service
Page 05 = Camera Service Tools



PLEASE contact Grass Valley Service BEFORE updating any software / package!!

Type	Description	FACT	Software		Package		INFO	Release Date	Release Note	FTP Link
			12nc	St.	12nc	St.				
LDX 80 Series	HD – Cam Head	8926 310 0xx01 8926 901 0xx01 8926 902 0xx01	>>	>>	6190	29	!!! V26 is REJECTED !!!	13.07.2016	SI-2117	Click me
LDX 82 Series	HD – Cam Head Elite	1-0108504-0000	>>	>>	538-00001-01	01	First Release			Click Me
LDX 86 Series	HD – Cam Head Worldcam HD – Cam Head High Speed HD – Cam Head Xtreme Speed HD – Cam Head 4K HD – Cam Head Universe	0086 305 00000 8926 903 00001 8926 906 00001 0086 322 00000 0086 326 00000	>>	>>	6436	16		25.01.2017	SI-2131	Click Me
LDX 86n Series	HD – Cam Head Worldcam HD – Cam Head High Speed HD – Cam Head Xtreme Speed HD – Cam Head 4K HD – Cam Head Universe	1-0108611-0000 1-0108613-0000 1-0108616-0000 1-0108614-0000 1-0108618-0000	>>	>>	6510	05	!!! Package V04 is not released !!!	19.01.2017	SI-2130	Click Me
FOCUS 70/75 Live	HD – Cam Head 1080i HD – Cam Head 720P HD – Cam Head 1080i/720P	0070 301 00000 0070 302 00000 0070 305 00000	>>	>>	6482	09	!!! V06 is REJECTED !!!	13.07.2016	SI-2117	Click Me
LDX Compact	HD – Cam Head Compact	8926 310 50001 8926 901 50001 8926 902 50001	>>	>>	6431	11	!!! V08 is REJECTED !!!	13.07.2016	SI-2117	Click Me
LDX Compact XS	HD – Came Head Compact XS	8926 906 50001	>>	>>	6467	04		21.09.2016	SI-2125	Click Me
LDX 5640	HD – 3 rd Gen. LDX Trx Adapter	8926 564 0xx01	--	--	6384	08		09.12.2015	SI-2100	Click me
LDX 5650	HD – 3 rd Gen. LDX Fib Adapter	8926 565 00001	--	--	6385	05		09.12.2015	SI-2100	Click me
LDX 5660	HD – XF Xtreme Sp. Adapter	8926 566 61001	--	--	6451	05	This package will be discontinued (See package LDX Universe)	07.05.2015	SI-2080	Click Me
LDX Universe	HD – XF Universe Adapter	0031 226 00200	--	--	6477	07	This package is also valid for the LDX XF Fiber adapter 8926 566 01001	10.05.2016	SI-2109	Click Me
FOCUS Triax	HD – FOCUS Triax Adapter	0018 203 1x000	--	--	6484	04		09.12.2015	SI-2102	Click Me
FOCUS Fiber	HD – FOCUS Fiber Adapter	0018 203 00200	--	--	6486	03		09.12.2015	SI-2102	Click Me
LDK 4426	HD – 3 rd Gen Conversion Box	8926 442 6xx01	--	--	6092	06		04.03.2013	SI-2011	Click me
LDK 4427	HD – 3 rd Gen Conversion Box	8926 442 7xx01	--	--	6252	02		04.03.2013	SI-2011	Click me
XCU 42xx Ser	XCU	8926 42x xxx01	>>	>>	6300	15	Version 12 is rejected	12.05.2016	SI-2113	Click me
XCU 4280	XCU – Xtreme Speed	8926 428 01001	>>	>>	6455	06		09.08.2016	SI-2121	Click Me
XCU Universe	XCU - Universe	0031 126 00200	>>	>>	6476	05		09.08.2016	SI-2118	Click Me
XCU IP	XCU – HD/4K XF IP	0032 122 00200	>>	>>	6478	04		25.10.2016	SI-2127	Click Me
FOCUS BU	Base Unit – FOCUS Triax Base Unit – FOCUS Fiber	0018 103 1x000 0018 103 00200	>>	>>	6488	05		10.05.2016	SI-2110	Click Me
LDK 4637	LDK Connect Gateway Server	8926 463 70001	--	---	5931	12		27.01.2016	SI-2107	Click me
LDK 4640	OCP 400	8926 464 0xx01	3810	32	--	--		09.08.2016	SI-2119	Click me
MCP 450	MCP450 Platform	8926 465 00001		0.03.005	--	--		29.01.2016	SI-2119	Click me
	Camera Connect application			1.15.0012	--	--		09.08.2016		
	MCP450 application			1.2.0.0	--	--		09.08.2016		
LDK 4475	ReFlex SXP	8926 447 50001	--	--	5897	05	Update recommended	08.08.2014	SI-2120	Click me
LDK 5303/20	HD – 2.7" EC270 OLED VF	8926 530 32001	--	--	6179	04		22.05.2015	SI-2082	Click me
LDK 5303/50	HD – 2" EC200 OLED VF	8926 530 35001	--	--	6507	01	First Release	13.07.2016		Click me
LDK 5307/00	HD – 7" LCD VF	8926 530 70001	--	--	5706	06		13.10.2015	SI-2095	Click me
LDK 5307/40	HD – 7.4" EC744 OLED VF	8926 530 74001	--	--	6453	02		05.12.2014	SI-2069	Click me
LDK 5309	HD – 9" LCD VF	8926 530 9xx01	--	--	5959	02		06.05.2013	SI-2019	Click me

PLEASE contact Grass Valley Service BEFORE updating any software / package!!



Type	Description	FACT	Service		Software		Package		INFO	Release Date	Release Note	FTP Link
			EoP	EoS	12nc	St.	12nc	St.				
DMC 1000/xx	"Infinity" Digital Media Camcorder	8926 100 0xx01	2010	31.12.2015	-	-	--	12.4	It's recommended use Release 12.4	09.03.2010	CRN-C12.4	Click me
LDK 3000 LDK 3000+	HD – Cmos Cam Head	8926 300 0x001	2012	2019	5631 5712	10	5662	12	5631 = Software for old Data Board (3922 406 52971) 5712 = Software for new Data-Board (3922 406 54991)	14.11.2014	SI-2070	Click me
LDK 4000 mkII	HD – Single Format Cam Head	8926 400 06x01	2008	31.12.2015	5070 5299	07 >>	-- >>	-- >>	! Old SW Platform → please contact GV Service for Update to new Software Platform ! SW / Package Release see LDK 8000 Elite !			
LDK 4000 Elite	HD – Single Format Cam Head	8926 400 07x01	2012	31.12.2019	5299	>>	>>	>>	! SW / Package Release see LDK 8000 Elite !			
LDK 8000	HD – Cam Head	8926 800 06x01	2008	31.12.2015	5070 5299	07 >>	-- >>	-- >>	! Old SW Platform → please contact GV Service for Update to new Software Platform ! SW / Package Release see LDK 8000 Elite !			
LDK 8000 Elite	HD – Cam Head	8926 800 07x01	2013	31.12.2020	5299	>>	5673 5674 5675 5676	15 15 19 26	Use Package-Advisor (see SW Tools)!	22.12.2015	SI-2104	Click me
LDK 8300	HD – 1x / 2x / 3x Slow Motion Cam Head	8926 830 00001	2018	31.12.2021	5218	09	5668	12		14.11.2014	SI-2070	Click me
LDK 8000 SportCam	HD – 1x / 2x Slow Motion Cam Head „SportCam“	8926 800 02x01	2010	31.12.2017	5299	20 20	5739 5740	02 01	Use Package-Advisor (see SW Tools)! Please be aware of LDK 4506 Software-Status!			Click me
LDK 5400 LDK 5430	SD – Triax Adapter	8926 540 0xx01 8926 543 0xx01	2009	31.12.2016	2505 5109	39 40	--	--	Enables TX (modulated Video in Triax) in Local-Mode TX Mode switchable only with new Data Board (52981)			Click me
LDK 5418	HD – 3 rd Gen. Trx Adapter	8926 541 8xx01	2014	31.12.2020	--	--	5831	04		07.09.2012	SI-2000	Click me
LDK 5420	HD – 3 rd Gen. Fib Adapter	8926 542 0xx01	2014	31.12.2021	--	--	5972	04		21.08.2014	SI-2052	Click me
LDX 5419	HD – 3 rd Gen. LDX Trx Adapter	8926 541 9xx01	2014	31.12.2020	--	--	6199	06		25.07.2013	SI-2049	Click me
LDX 5421	HD – 3 rd Gen. LDX Fib Adapter	8926 542 1xx01	2014	31.12.2020	--	--	6200	07		04.08.2014	SI-2053	Click me
LDK 5450	SD – Wireless Adapter "SDW-WCA"	8926 545 00x01	2008	31.12.2015	3813 5115	07 08	--	--	LDK 100-200 supported since SW-Status 49 - LDK 300-500 supported since SW Status 10 SW-Rel. Status.07: Improvement of reliability, Filemanagement	10.04.2008	SI-1141	Click me
LDK 5464	HD – Wireless Adapter "HDW WCA"	8926 546 4xx01	2012	31.12.2019	4919	06	HW	1.3	Actual HW-Revision: v1.3 – Ask your local Grass Valley Engineer Please be aware of LDK 4470 Software-Status!			Click me
LDK 5490	HD – "Viper" Adapter	8926 549 00001	2011	31.12.2017	--	--	--	--				
LDK 5630	HD – LDK 3000 Triax Adapter	8926 563 0xx01	2012	31.12.2019	---	--	5663	01		28.04.2011	SI-1253	Click me
LDK 5860	HD – Triax Adapter HD 1x / HD 2x	8926 586 0xx01	2010	31.12.2017	5097	05	5677	04	Package V03 is not released	13.02.2014	SI-2038	Click me
LDK 5861	HD – Triax Adapter "Dynamic Air" - HD 1x / HD 2x	8926 586 1xx01	2013	31.12.2020	--	--	5857	01	BaseStation need to be updated to support new Adapter! Check SW & FW Status of LDK 4502 = SW Status >= Status.20 and FW Status >=Status.07			Click me
LDK 5880	HD – Fiber Adapter HD 1x / HD 2x / HD 3x	8926 588 0xx01	2011	31.12.2018	--	--	5669	11	! BaseStations need to be updated to support new adapter package !	21.08.2014	SI-2052	Click me

PLEASE contact Grass Valley Service BEFORE updating any software / package!!



Type	Description	FACT	Service		Software		Package		INFO	Release Date	Release Note	FTP Link
			EOp	EOs	12nc	St.	12nc	St.				
LDK 4450	SD – Wireless Control Unit "SDW WCU"	8926 445 0xx01	2008	31.12.2015	4326	06	HW	1.11	Improvement of RF-Link - Support of File-Management	10.04.2008	SI-1140	Click me
LDK 4470	HD – Wireless Control Unit "HDW WCU"	8926 447 0xx01	2012	31.12.2019	5160	07	--	--	Actual HW-Revision: v1.3 – Ask your local Grass Valley Engineer Please be aware of LDK 5464 Software-Status!	25.10.2013	SI-2033	Click me
LDK 4400	HD – 3 rd Gen. Triax BaseStation	8926 440 0xx01	2014	31.12.2020	>>	>>	5806	12		30.09.2015	SI-2094	Click me
LDK 4410	HD – 3 rd Gen. 3Gig Fiber Bs	8926 441 0xx01	2014	31.12.2020	>>	>>	5973	08		16.04.2015	SI-2081	Click me
LDK 4420	HD – 3 rd Gen. Dual BaseStation	8926 442 0xx01	2014	31.12.2020	>>	>>	6021	08		16.04.2015	SI-2081	Click me
LDK 4430	HD – 3 rd Gen 3x Fiber BS	8926 443 0xx01	2014	31.12.2020	>>	>>	5974	08		16.04.2015	SI-2081	Click me
LDK 4501	SD – "Slim Line" Base Station	8926 450 10101	2009	31.12.2016	3307 (TWB)	37	--	--				Click me
					3803 (C1P)	10	--	--				
LDK 4502/02	HD – BaseStation - Triax	8926 450 20101	2011	31.12.2018	3804 (C1P)	27	--	--		01.09.2013	SI-2030	Click me
LDK 4503	HD – BaseStation - Fiber	8926 450 3xx01	2009	31.12.2016	>>	>>	>>	>>				
LDK 4506	HD – 1x / 2x BaseStation – Triax	8926 450 6xx01	2010	31.12.2017	4172	12	--	--	NEW: Support LDK 5861 Dynamic Air® and LDK Connect Gateway	21.03.2011	SI-1248	Click me
LDK 4580	HD – LDK 3000 BaseStation	8926 458 0xx01	2011	31.12.2018	5632	06	5664	11	Support only LDK 3000 + LDK 5630	16.04.2015	SI-2081	Click me
LDK 4582	HD – 3Gig BaseStation - Fiber	8926 458 2xx01	2011	31.12.2018	>>	>>	5671	14	! Fiber Adapters need to be updated to support new adapter package !	16.04.2015	SI-2081	Click me
LDK 4583	HD – 1x / 2x / 3x BaseStation – Fiber	8926 458 3xx01	2011	31.12.2018	>>	>>	5670	13	! Fiber Adapters need to be updated to support new adapter package !	16.04.2015	SI-2081	Click me
LDK 4488 LDK 4489	Super XPander XPander	8926 448 8xx01 8926 448 9xx01	2011	31.12.2018	5105	07	--	--	CLASS support	04.03.2013	SI-2011	Click me
LDK 4020/00	HD – 7" Viewfinder	8926 402 00001	2009	31.12.2016	5107	02	--	--				Click me
LDK 4020/20	HD – 7" Viewfinder	8926 402 02001	2008	31.12.2015	5107	02	--	--				Click me
LDK 4021	HD – 7" Viewfinder	8926 402 1xx01	2013	31.12.2019	5230	01	--	--				Click me
LDK 4630	MCP 400	8926 463 00001	2014	31.12.2017	4029	17	--	--		11.09.2014	SI-2058	Click me

For all products with "EProm" please contact GV Service / TAC Camera



Type	Description	FACT	Service		Software		Package		Info	Release Date	Release Note	FTP Link
			EoP	EoS	12nc	St.	12nc	St.				
LDK 100 LDK 110 LDK 120 LDK 150 LDK 200	SD – Cam Head	8926 010 0xx01 8926 011 0xx01 8926 012 0xx01 8926 015 0xx01 8926 020 0xx01	2003 2004 2004 2004 2003	31.12.2010	2793	→	---	---	Last release with SW 12nc: 2793 = Status.50 SW replaced with LDK 300 – 500 Software, 12nc: 4020 !			Click me
LDK 6000	HD – Cam Head	8926 600 00x01	2002	31.12.2009	3391	31	---	---				Click me
LDK 4000	HD – Single Format Cam Head	8926 400 00x01	2007	31.12.2014	4460 5074	05	--	--		29.09.2010	SI-1233	Click me
LDK 5000	HD prepared Cam Head	8926 500 00001	2007	31.12.2014	3780 5075	12	--	--		29.09.2010	SI-1233	Click me
LDK 6000 mkII	HD – Cam Head	8926 600 0xx01	2007	31.12.2014	3391 5076	31	--	--		29.09.2010	SI-1233	Click me
LDK 6200	HD – Slow Motion Cam Head	8926 620 00001	2007	31.12.2014	4158 5077	08	--	--		29.09.2010	SI-1233	Click me
LDK 7500	HD – Cam Head „Viper“	8926 750 00001	2007	31.12.2014	3774	11	--	--	No support of Data Brd 3922 406 52971!			Click me
LDK 300 LDK 400 DPM LDK 400 ITW LDK 500	SD – Cam Head	8926 0x0 0x001 8926 0x0 0x101 8926 0x0 0x201 8926 0x0 0x301	2007 2007 2007 2009	31.12.2014 31.12.2014 31.12.2014 31.12.2014	4020 5073	23	--	--				Click me
LDK 5460	HD – Triax Adapter	8926 546 0xx01	2007	31.12.2014	3435 5111	13 14	--	--	Enables TX (modulated Video in Triax + Fiber) in Local-Mode TX Mode switchable only with new Data Board (52981)			Click me
LDK 5462	HD – Slow Motion Triax Adapter	8926 546 2xx01	2007	31.12.2014	4169 5112	05 06	--	--	TX Mode switchable only with new Data Board (52981)			Click me
LDK 4058	SD – Slow Motion Base Station	8926 405 8xx01	2006	31.12.2013	2712	44	--	--	ONLY in combination with SW-Update of Cam Head!! → LDK 23 / LDK 23mkII			EProm
LDK 4502/01	HD – BaseStation - Triax	8926 450 20101	2003	31.12.2013	3425 (TWB)	30	--	--	S9000 - Only support cameras till LDK 6000, not supported anymore!			Click me
LDK 4505	HD prepared – Base Station for LDK 5000	8926 450 5xx01	2007	31.12.2014	3782 (TWB) 3805 (CIP)	03 11	--	--				Click me
LDK 110 (D) LDK 120 (D) LDK 150 (D) DCR 20 (D) DCR 50 (D)	SD – DVCPPro 25 Adapter SD – DVCPPro 50 Adapter	8926 011 0xx01 8926 012 0xx01 8926 015 0xx01 8926 551 0xx01	2003	31.12.2010	2503	17	---	---				Click me
LDK 4607	MCP (1) – S9000	8926 460 70x01	2006	31.12.2013	3570	95	--	--	Final Release! Support all Cameras till LDK 6000			EProm
LDK 4609	MCP (2) – S9000	8926 460 90x01	2006	31.12.2013	2090	35	--	--	Final Release! Support all Cameras till LDK 6000			EProm
LDK 4624	OCP (-1 – Joystick) – S9000	8926 462 4xx01	2006	31.12.2013	1233	82	---	---	Final Release! Support all cameras till LDK 6000			EProm
LDK 4628/00	OCP (-2 – Rotary) – S9000	8926 462 80001	2006	31.12.2013	1215	87	---	---	Final Release! Support all cameras till LDK 6000			EProm
LDK 4628/05	OCP (-2 – Rotary) – S9000	8926 462 80501	2006	31.12.2013	2596	12	---	---	Final Release! Support all cameras till LDK 6000			EProm
LDK 4629/00	OCP (-2 – Joystick) – S9000	8926 462 90001	2006	31.12.2013	2152	87	--	--	Final Release! Support all Cameras till LDK 6000			EProm
LDK 4629/05	OCP (-5 – Joystick) – S9000	8926 464 90501	2006	31.12.2013	2597	12	--	--	Final Release! Support all Cameras till LDK 6000			EProm
LDK 4636	CIP Data-Board for LDK 405x	8926 463 60001	2006	31.12.2013	4110	05						Click me

For all products with "EProm" please contact GV Service / TAC Camera

PLEASE contact Grass Valley Service BEFORE updating any software / package!!



Description	Software		INFO	Release Date	Release Note	FTP Link
	12nc	St.				
LDK Scripser – Update Tool for LDK and LDX Systems	3579	v09.00	Windows issues resolved	28.02.2014		Click me
Win-Driver for Grass Valley Service Dongle (J-Tag Dongle)		V2.04.16				Click me
Package Advisor for LDK 4000 / 8000 / 8000 Sport Cam	5754	02_01	PackageAdvisor_392240757541_S02_01			Click me
Package Advisor for VF 5303/20 – LDK 5303/50 – 5307/00 – 5307/40 - 5309		01_02	PackageAdvisor_Viewfinders_S01_02	11.07.2016		Click me
“Collect Data Scripts” To collect Brd / SW / FW Status from Camera Parts	Collect “Camera Data” - Script	v1.12				Click me
	Collect “VF Data” – Script (only no-tube)	v2.00				Click me
	Collect “Camera Adapter Data” – Script	v2.11				Click me
	Collect “Conversion Box Data” – Script	v0.30				Click me
	Collect “BaseStation Data” - Script	v1.4				Click me
	Collect “LDXCameraData” – Script	V3.01		28.03.2014		Click me
	Collect “LDXAdapterData” – Script	v1.0		22.02.2013		Click me
	Collect “XCUData” – Script	V2.02	V2.02 for 4K and IP XCU	03.03.2015		Click me
Wireless Insight Tool for GV SD- & HD-Wireless		v2.3	Uninstall all earlier versions and use only this version!			Click me
PCDown - update tool for LDK10 / LDK20						Click me



PLEASE contact Grass Valley Service BEFORE updating any software / package!!

Download method for actual LDK and LDX products!

Due to the fact that all components within a camera today in mostly based on Software, Firmware and Boot Software and that there is a direct influence of the compatibility to each other, we changed the process of Software Updates some while ago to a PACKAGE loading!

These Packages includes all necessary Firmware and Software parts which are necessary for a camera part to run reliable.

For the following Products we only provide Packages which includes all necessary Software to make a proper, reliable update of your Equipment:

- LDK 3000
- LDK 4000 (MKII + Elite)
- LDK 8000 (+ Elite)
- LDK 8300
- LDX Cameras Series

- LDK 5418
- LDX 5419 – LDX Adapter
- LDK 5420
- LDX 5421 – LDX Adapter
- LDX 5630 – LDK 3000 Adapter
- LDX 5640, LDX 5650, LDX 5660
- LDK 5860, LDK 5861
- LDK 5880

- LDK 4400, LDK 4410, LDK 4420, LDK 4430
- LDK 4580, LDK 4582, LDK 4583
- LDK 42xx – XCU Series
- LDK 4475
- LDK 4426, LDK 4427

- LDK 5303/20 LCD VF Eye Catcher
- LDK 5307/00 LCD VF
- LDK 5307/40 LCD VF OLED
- LDK 5309 LCD VF

If a system detects inconsistent Software / Firmware combinations you'll automatically get a warning message in your Viewfinder. If this is the case we urgently recommend updating this camera immediately!

You can find the Package Information in the VF Menu: Main /Diagnostics /Package
Please get in contact with your local Grass Valley Service Engineer for more details!



PLEASE contact Grass Valley Service BEFORE updating any software / package!!