

IRD-3802/3811 – Upgrade Package 4.0.3

Upgrade Package Release History

Release Version	Comprising:		Release Date	Version Details	User Manuals for this release (Grass Valley document #)
	Firmware Version	Software Version			
4.0.3	n/a	4.0.3	2015.09.14	(go)	M837-8800-105 M837-9600-204
4.0.2	n/a	4.0.2	2015.03.03	(go)	M837-8800-105 M837-9600-204

NOTES: The iControl compatibilities shown below are officially supported by Grass Valley. Earlier versions may also work, with bugs or limited features.

The Reference number (Ref#) given for each feature or bug in these Release Notes refers to internal Grass Valley documentation.

WARNING: This upgrade package contains only the iControl Service upgrade for IRD-3802/3811 FW 4.0.3 on iControl version 5.0+. You will need to upgrade the Firmware separately with Miranda Update Utility using separate instructions provided in the IRD Series Firmware Release Notes.

UPGRADE PACKAGE: 4.0.3

Release date: [2015-09-14](#)

iControl compatibility: [5.0 \(build 17\)](#)

iControl Solo compatibility: [6.0 \(build 89\)](#)

RCP-200 compatibility: [RCP-200 support version 1.8.2 via application server only * limited support.](#)

Custom software compatibility: [NA](#)

Hardware compatibility: [This upgrade package applies to all existing hardware assemblies but is not supported for IRD-3801 or IRD-31NN models.](#)

ENHANCEMENTS & NEW FEATURES

Ref#	Description

BUGS FIXED IN THIS RELEASE

Ref #	Description
DSERV-1379	Audio Processing Levels not responding in 402 RC-1 upgrade package.

KNOWN BUGS & LIMITATIONS

Ref #	Description
DSERV-1077	Limitations using RCP200 <ul style="list-style-type: none">The RCP200 will not be able to control IRD cards in standalone mode; service is not available.Support of DVB-S tuner is not implementedAnalog functions have not been removed to reflect the IRD 4XX firmware

IMPORTANT: For full card release notes, please refer the IRD Series Firmware Release Notes.

UPGRADE PACKAGE: 4.0.2

Release date: 2015-03-03

iControl compatibility: 5.0 (build 17)

iControl Solo compatibility: 6.0 (build 89)

RCP-200 compatibility: RCP-200 support version 1.8.2 via application server only * limited support.

Custom software compatibility: NA

Hardware compatibility: This upgrade package applies to all existing hardware assemblies but is not supported for IRD-3801 or IRD-31NN models.

ENHANCEMENTS & NEW FEATURES

Ref#	Description
DSERV-1077	In Network settings, the Streaming mode VBR/CBR has been implemented.

BUGS FIXED IN THIS RELEASE

Ref #	Description
DSERV-916	Y-Gain offset control was not functioning correctly in RCP200

KNOWN BUGS & LIMITATIONS

Ref #	Description
DSERV-1077	Limitations using RCP200 <ul style="list-style-type: none">The RCP200 will not be able to control IRD cards in standalone mode; service is not available.Support of DVB-S tuner is not implementedAnalog functions have not been removed to reflect the IRD 4XX firmware