

[Internal Use Only] <<The information in this document should not be used for other purpose than Sony and/or Sony authorized dealers (ASC/ASD).>>

Sony IP&S Inc.

No. HDCM19-026R-TN

Technical News

Issued : May 17, 2019

Revised : September 4, 2019

Subject: Software Release [MAIN V3.30 => V3.40]

[Applicable Model]

Model / Destination	Serial Number	Number of Unit
RCP-1500 SYM		
RCP-1501 SYM		
RCP-1530 SYM		

(Rev.1) The [Note] is added. The software file is not changed.

[Description]

Updated version of the software (MAIN: V3.30 => V3.40) for RCP-1500/1501 and 1530 is released.
Upgrade it as necessary.

[Note] When connecting to HDCU3100/3500/5500 via CNU-700, be sure to upgrade to this version.
If the version is V3.30 or lower, the error that the operation of CNU-700 stops occurs. (Rev.1)

[Change Points]

<Added Functions>

1. The OETF setting of transfer format is supported.
Multi Format menu, BPU Multi Format menu
2. The settings of input return for HDCU3100/3500/5500 are supported.
Return Settings menu
Settings up to 8Ch are supported.
Setting for 4K Return is supported.

[Preparation]

<Memory Stick>

Version upgrade is executed using a Memory Stick Duo or a Memory Stick PRO Duo.

<Software File>

File name:

Upgrade file for MAIN/LOADER BLOCK: RCP15XX.ROM

* Please contact to your local Sony's service office for obtaining the software file.

Create a folder having the name shown below in a Memory Stick, and copy the above file in it.
\\MSSONY\\PRO\\CAMERA\\RCP15XX

[Installation Procedure]

Refer to the section of "Firmware Update" in the Maintenance Manual.

[Confirmation / Adjustment]

Confirm if the version of the MAIN is V3.40 and the version of the LOADER is V2.10.

* Refer to the section of "Firmware Update" in the Maintenance Manual for the method of checking the version number.