


To reset the Management IP to the Default IP Address 192.168.1.1 you will need an empty USB key. From your PC, please open Notepad and save a blank file.



Please save this file as "XNet" including the quotation marks. You can leave the file type as a .txt.

File name: "XNet"
Save as type: Text documents (*.txt)

Once this file has been moved to the USB Key, please plug this USB Key into the back of the XHub under the MGMT port.



USB
connector

Once the USB key is plugged into the XHub. Please go to the front of the XHub and press the reset button for 4 seconds.



Reset

Once these steps have been completed, you can remove the USB key.

