



A **BELDEN** BRAND

Technical Note

NV9000 Security Update

Introduction

Certain NV9000 system controllers might have been infected with the “Conficker” virus.


You can obtain a patch for this virus from Microsoft at:

<http://www.microsoft.com/en-us/download/details.aspx?id=3205>

Download the patch, copy it to a clean USB stick, and run the installer on the NV9000 system controller.

Download


- 1 Go to <http://www.microsoft.com/en-us/download/details.aspx?id=3205>:



Click 'Download'.

NV9000 Security Update

2 A dialog appears:



Click 'Save File'.

A window appears in which you can navigate to the folder in which you want to save the file. Save the file. Its name is WindowsXP-KB958644-x86-ENU.exe.

3 Copy the file to a USB device in preparation for installing the patch on each NV9000 system controller.

Installing the Patch

Login on the NV9000 system controller.


1 Insert the USB device in a USB slot. Open the folder into which you copied the patch installer.

2 Double-click the patch installer. The initial window appears:




Click 'Next'.

3 A license agreement window appears:




Choose 'I agree' and click 'Next'.

4 The installer proceeds and gives you a progress indicator:



NV9000 Security Update

5 When the installer has finished, it presents its final window:



Check 'Do not restart now' if you do not want to restart your controller immediately.
Click 'Finish' to complete the installation.

6 Eventually you must restart the controller for the patch to take effect.

More Information

More information (and installers for other OS applications) can be obtained from Microsoft at this address:
<http://technet.microsoft.com/en-us/security/bulletin/ms08-067>