Errata

DPS-575 Digital Processing Synchronizer Installation and Operation Manual

About this Document

This document shows one correction in Chapter 2 on page 10 of the DPS-575 Digital Processing Synchronizer Installation and Operation Manual, Edition C.

Please replace the paragraph under "Composite Video Output" with the following text:

Composite Video Output

These BNC connectors, labeled **Comp 1 Out** and **Comp 2 Out**, provide processed, synchronized/timebase-corrected versions of any of the input signals. If the unit is set to **Bypass** mode, the Composite Input is bypassed directly to the Comp 1 output (the leftmost of the two connectors), providing an unprocessed signal. Comp 2 Out provides a black output when Bypass is selected. The Comp 1 input is automatically bypassed to the Comp 1 Out output when the unit is off.

