



The Ocelot Audio Regulator – 81906519220 will not have a thermistor installed in the R10 position whereas the video regulator does. Other noticeable differences are in the capacitor sizes. (C7 & C18)