

Sony Corporation

No. HDVM06-078-TN

Technical News

Issued : April 17, 2007

Subject: Software Version Up HDCU1000/HDCU1500 V1.06

Applicable Model(s) (Destination)	Serial Number(s)		Number of Unit(s)
HDCU1000/L CED	40001	- 40013	13
HDCU1000/L J2	31021	- 31029	9
HDCU1000/L UC5	10001	- 10060	60
HDCU1000/L1 CED	41001	- 41085	85
HDCU1000/L1 UC5	11001	- 11112	112
HDCU1000/L2 CED	42001	- 42125	125
HDCU1000/L2 UC5	12001	- 12140	140
HDCU1000/T J2	30001	- 30035	35
HDCU1000/T1 J2	31001	- 31020	20
HDCU1000/T2 J2	32001	- 32015	15
HDCU1500/L SYL	10001	- 10025	25
HDCU1500/L1 SYL	11001	- 11089	89
HDCU1500/L2 SYL	12001	- 12175	175
HDCU1500/T J4	30001	- 30015	15
HDCU1500/T1 J4	31001	- 31060	60
HDCU1500/T2 J4	32001	- 32045	45

This Technical News includes information on Software Version Upgrade. Please contact to your local Sony's sales/service office for the details.