



Electronic Viewfinder

Video Products Technical Bulletin 30-2012-008

DATE: **February 6, 2012**SUBJECT: **PARTS REGISTRATION—SUBSTITUTE FOR
P BOARD**MODEL: ***DXF-51***
DXF-51SERIAL NO: **ALL***Italicized information in green applies to
customers outside the United States.*

DESCRIPTION

When the P board needs to be replaced, use the VF-83 board as a substitute:

FormerP board
9-939-889-02**New**VF-83 board
A-1114-130-A

NOTE: The VF-83 board is lead free. The P board is no longer available.

ORDERING INFORMATION

To order parts online, go to: www.sony.com/servicesplus. For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

DXCM12-001