
Table of Contents

Laser Safety	iv
FCC Part A Manual Notice	iv
Warning CE	iv
Introduction	1
Setup	1
Packing List	1
Attaching the Rack Mount Adapters	2
Line Power	2
Configuring Signal I/O	3
Rear Panel Connections	3
Front Panel Indicators and Control	3
System Example	4
Fiber Optic Cable Runs	5
Making the Fiber Connection	6
Optical Transmitter Losses	6
Power Switch	7
System Block Diagrams	7
Battery Pack	9
Repair	9
Accessory List	9
Troubleshooting	10
Specifications	11
Warranty	12

List of Figures

Figure 1.	Installing the Rack Mount Adapters	2
Figure 2.	Diamondback Rear Panel	3
Figure 3.	Front Panels, RX (Upper) and TX (Lower)	3
Figure 4.	Example of the DiamondBack/Adder 161	5
Figure 5.	TX Block Diagram	8
Figure 6.	TX Input Schematic	8
Figure 7.	RX Block Diagram	9
Figure 8.	RX Output Schematic	9

List of Tables

Table 1.	Power Input Pin-outs	2
Table 2.	Optical Loss Margin	7
Table 3.	Troubleshooting Chart	11