



Customer Service BULLETIN

Severity Level: **Low**

Distribution

- WW ☒
- APAC ☐
- EMEA ☐
- JAPAN ☐
- LATAM ☐
- NAM ☐

Internal Only ☐

Customer Service Bulletin

24206

Title Camera Connect Software update V1.67.0039

Date 2021-07-22

Product CCS-One Camera Control Server and MCP 450

Product Version Camera Connect application

Overview

System parts involved:

- CCS-One Cameras Control Server
- MCP 450 Box PC

Overall Message

The Camera Connect Application is available for the CCS-One and MCP450

After updating the software, the new status of the Camera Connect application becomes version **1.67.0039**


There are 2 installers available:

- For the CCS-One installer “Camera Connect for **CCS-One v1.67.0039.exe**” to be used.
- For the MCP 450 installer “Camera Connect for **MCP450 v1.67.0039.exe**” to be used.

Note: For installation on the CCS-One, the CCS-One Platform minimum version **v0.04.0004** need to be installed.

New functionality: (In combination with LDX 100 SW/FW Package v06)

- Overall Jpeg XS On/Off
- Jpeg XS settings for Main, Live and High Speed video streams (Compression Ratio + Header Yes/No)



- Secondary Monitoring stream enable On/Off (for XCU IP redundancy)

Contacts

Grass Valley Product Support

For or technical assistance, please contact us by e-mail or phone. For more information refer to:
<http://www.grassvalley.com/support/contact>

Overview

For an overview of released camera service bulletins, fault descriptions, related products and filter options, refer to:
<https://community.grassvalley.com/>