

[Internal Use Only] <<The information in this document should not be used for other purpose than Sony and/or Sony authorized dealers (ASC/ASD).>>

Sony Corporation

No. HDCM16-024-TN

Technical News

Issued : July 15, 2016

Subject: Software Release [AT software: V2.20]

[Applicable Model]

Model / Destination	Serial Number	Number of Unit
HDFX200 CED	- 40325	
HDFX200 UC7	- 10314	

[Description]

Updated software for the HDFX200 (V2.20) is released.
Upgrade it as necessary.

[Change Point]

- Correct the error of the remote switching in Single mode fiber mode.
When the HDFX200 which the HKC-SM27 is installed is in the single mode fiber mode and the system is connected to the MCS, the error that the mode of HDFX200 may be switched by selecting the applicable system as the camera from the MSU. It is corrected.

[Preparation]

<Software File>

File name: hdfx200_app.pkg - software file

* Please contact to your local Sony's service office for obtaining the software file.

<Others>

USB memory 1 piece

[Installation Procedure]

Install the software by referring to the description in the MAINTENANCE MANUAL.

[Confirmation/Adjustment after Installation]

Confirm the versions of HDFX APP in the HDFX menu DIAGNOSIS – <ROMVERSION> (D2) page. Also confirm if the versions of the PLD are the latest ones described below.

ADAPTOR APP	V2.20 (Corrected item)
POST PLD	V1.03
DEMUX PLD	V1.04