

# iAM-MIX(IP) Software Release Notes

## RELEASE VERSION – 2.8-25

Release Date: **February 15<sup>th</sup>, 2019**

## RELEASE FEATURES

- New preset creation page with Input Matrix for various inputs on the Web UI.
- Updated Dashboard on the Web UI.
- Support for creating and recalling up to 64 Presets from the web UI.
- Support for creating 8 (for iAm-MixIP 8) or 16 (for iAm-MixIP 16) favorite presets from Web. By default the Favorite presets will be shown, if no favorite are present then random Presets will be shown according.
- Device operation through Restful APIs.
- Support for 2110 and 2022-6 SFP's.
- Output Routing support that enables users to control how various outputs are configured and which monitored signals are routed to various outputs.
- Ability to download System logs from the web UI.
- Displays SFP information on the web UI.
- Ability to view User Manual as well as the Restful API documentation from within the web UI of the unit.

## KNOWN LIMITATIONS

- **Since this is a major release it is requested to back-up the presets using import preset feature before applying this upgrade.**
- The status for "Mute on Headphone insertion" on Web is not correct when license is disabled.
- If DHCP has been set and the LAN cable is not connected then in this scenario it will take longer time to boot.
- For iAm-MixIP 16, the 16<sup>th</sup> channel will be set as Master Volume. The master volume can be enabled/disabled from the web UI.
- Dolby option is not yet available.
- Remote upgrade is expected to take 5 minutes for target unit to be upgraded. Avoid performing any operation on source or target unit during that time.
- Avoid pressing buttons on front panel and clicking buttons on web GUI simultaneously. Results may be inconsistent.

- Due to character size of the OLED display, some label strings may be truncated on the right edge.
- The unit supports 64-channel MADI with 48 KHz sample rate only.
- Use FAT32 formatted USB disk for software upgrade and preset import/export.

# SOFTWARE RELEASE NOTES

iAM-MIX 2.7-27

Revision 1.0

Dec 14, 2018

## HEADLINE FEATURE

Resolves issue where some MADI sources were did not processed correctly

## KNOWN LIMITATIONS

- 'Dolby' option is not available in current version
- User will have to 'Apply preset' post importing USB preset from web GUI. Not doing so will cause unit to go back to the preset before it got loaded upon boot up
- Remote upgrade is expected to take 5 minutes for target unit to be upgraded. Avoid performing any operation on source or target unit during that time
- Mute/Unmute status of channel on web GUI does not apply for Master volume post enabling Master mode
- Avoid pressing buttons on front panel and clicking buttons on web GUI simultaneously. Results may be inconsistent
- Pushing labels from Evertz or Tally while unit is in menu mode will have incorrect mute/unmute status while trying to exit. It can be recovered by pressing hold for solo on any channel
- Due to character size of the OLED display, some label strings may be truncated on the right edge
- The unit supports 64-channel MADI, with 48 kHz sample rate only

## NOTES

- For setting the IP address, It is only necessary to save values the user wants changed, the others are copied as they existed at the last boot
- Additional options like fiber optic support etc. are available upon request
- Please reboot unit after restoring database from GUI
- Use FAT32 format USB stick to upgrade to new version
- Credentials to log in to database management is **User name-** [admin](#) **Password-** admin
- Although it works on all major browsers we recommend using Chrome for all major operation

# SOFTWARE RELEASE NOTES

iAM-MIX 2.7-9

Revision 1.0

Oct 19, 2018

## HEADLINE FEATURE

Multi Evertz labels support

Resolves issue where some MADI sources were did not processed correctly

## KNOWN LIMITATIONS

- 'Dolby' option is not available in current version
- User will have to 'Apply preset' post importing USB preset from web GUI. Not doing so will cause unit to go back to the preset before it got loaded upon boot up
- Remote upgrade is expected to take 5 minutes for target unit to be upgraded. Avoid performing any operation on source or target unit during that time
- Mute/Unmute status of channel on web GUI does not apply for Master volume post enabling Master mode
- Avoid pressing buttons on front panel and clicking buttons on web GUI simultaneously. Results may be inconsistent
- Pushing labels from Evertz or Tally while unit is in menu mode will have incorrect mute/unmute status while trying to exit. It can be recovered by pressing hold for solo on any channel
- Due to character size of the OLED display, some label strings may be truncated on the right edge
- The unit supports 64-channel MADI, with 48 kHz sample rate only

## NOTES

- For setting the IP address, It is only necessary to save values the user wants changed, the others are copied as they existed at the last boot
- Additional options like fiber optic support etc. are available upon request
- Please reboot unit after restoring database from GUI
- Use FAT32 format USB stick to upgrade to new version
- Credentials to log in to database management is **User name-** [admin](#) **Password-**admin
- Although it works on all major browsers we recommend using Chrome for all major operation

# SOFTWARE RELEASE NOTES

iAM-MIX 2.7-3

Revision 1.0

June 26<sup>th</sup>, 2017

## HEADLINE FEATURE

Multi Evertz labels support

## KNOWN LIMITATIONS

- 'Dolby' option is not available in current version
- User will have to 'Apply preset' post importing USB preset from web GUI. Not doing so will cause unit to go back to the preset before it got loaded upon boot up
- Remote upgrade is expected to take 5 minutes for target unit to be upgraded. Avoid performing any operation on source or target unit during that time
- Mute/Unmute status of channel on web GUI does not apply for Master volume post enabling Master mode
- Avoid pressing buttons on front panel and clicking buttons on web GUI simultaneously. Results may be inconsistent
- Pushing labels from Evertz or Tally while unit is in menu mode will have incorrect mute/unmute status while trying to exit. It can be recovered by pressing hold for solo on any channel
- Due to character size of the OLED display, some label strings may be truncated on the right edge
- The unit supports 64-channel MADI, with 48 kHz sample rate only

## NOTES

- For setting the IP address, It is only necessary to save values the user wants changed, the others are copied as they existed at the last boot
- Additional options like fiber optic support etc. are available upon request
- Please reboot unit after restoring database from GUI
- Use FAT32 format USB stick to upgrade to new version
- Credentials to log in to database management is **User name-** [admin](#) **Password-**admin
- Although it works on all major browsers we recommend using Chrome for all major operation