

ISO Transformer Pinout

Input	
DB-25 (male)	
1	Transformer #1 (+) high
2	Transformer #2 (+) high
3	Transformer #3 (+) high
4	Transformer #4 (+) high
5	Transformer #5 (+) high
6	Transformer #6 (+) high
7	Transformer #7 (+) high
8	Transformer #8 (+) high
9	Transformer #9 (+) high
10	Transformer #10 (+) high
11	n/c
12	n/c
13	n/c
14	Transformer #1 (-) low
15	Transformer #2 (-) low
16	Transformer #3 (-) low
17	Transformer #4 (-) low
18	Transformer #5 (-) low
19	Transformer #6 (-) low
20	Transformer #7 (-) low
21	Transformer #8 (-) low
22	Transformer #9 (-) low
23	Transformer #10 (-) low
24	n/c
25	n/c

Output	
DB-25 (male)	
1	Transformer #1 (+) high
2	Transformer #2 (+) high
3	Transformer #3 (+) high
4	Transformer #4 (+) high
5	Transformer #5 (+) high
6	Transformer #6 (+) high
7	Transformer #7 (+) high
8	Transformer #8 (+) high
9	Transformer #9 (+) high
10	Transformer #10 (+) high
11	n/c
12	n/c
13	n/c
14	Transformer #1 (-) low
15	Transformer #2 (-) low
16	Transformer #3 (-) low
17	Transformer #4 (-) low
18	Transformer #5 (-) low
19	Transformer #6 (-) low
20	Transformer #7 (-) low
21	Transformer #8 (-) low
22	Transformer #9 (-) low
23	Transformer #10 (-) low
24	n/c
25	n/c